

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHA2622S

Make : HYUNDAI

Model : IONIQ(G3)

Date: 05.08.2022

Insurance: NTUC

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			<i>Ry</i> \$459.40
10	REAR BUMPER CLIPS			<i>ne</i> \$22.00
1	REAR BUMPER CENTRE MOULDING ASSY			<i>de</i> \$451.25
1	REAR BUMPER REINFORCEMENT			\$394.80
1	ANTENNA SMARTKEY			<i>nt</i> \$40.50
1	REAR BUMPER FOG LAMP			<i>x</i> \$201.50
1	LICENCE LAMP			<i>L x</i> \$85.30
	SUB TOTAL		<i>473.25</i>	\$1,654.75
	LESS 20%		<i>378.60</i>	\$330.95
	DISCOUNTED TOTAL			\$1,323.80
	REAR NUMBER PLATE WITH TRIM COVER			<i>Cur</i> \$55.00
	REAR BUMPER REVERSE SENSOR			<i>su</i> \$180.00
			<i>10% - 211.50</i>	\$235.00
	Labour Charge			
	PANEL BEATING			<i>350</i> \$400.00
	SPRAY PAINTING CHARGE			<i>250</i> \$300.00
	REMOVE/REFIX REVERSE SENSOR			<i>30</i> \$80.00
	TOTAL LABOUR		<i>630</i>	\$780.00
	ESTIMATE TOTAL		<i>1220.10</i>	\$2,338.80
			<i>4581.000</i>	
			<i>02 days</i>	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanfer 97495749
'wp' 5/8/2020 330pm
12 days
Tanfer @ LK Auto Consultants
to

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: