

COMFORTDELGRO ENGINEERING PTE LTD

✓ SAS - KLV → see attached.

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

DATE: 04.08.2022
 MODEL: Hyundai Ioniq
 VEHICLE NO.: SHA7019B

(Police report attached)

INSURANCE: NTUC (US)
 MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Front Bumper	1		\$ 481.10
	Front Bumper Clips	10	\$ 2.20	\$ 22.00
	Front Bumper Upper Moulding	1		\$ 368.50
	Front Bumper Lower Grille	1		\$ 368.50
	Front Bumper Side Brkt RH	1		\$ 35.00
	Headlamp RH	1		\$ 2,110.30
	DayLight RH	1		\$ 642.50
	DayLight Grille RH	1		\$ 93.45
SUB TOTAL				\$ 4,121.35
LESS 20%				\$ 824.27
TOTAL SPARE PARTS				\$ 3,297.08
Labour Charge				
	Panel Beating			\$ 400.00
	Spray Painting			\$ 300.00
	Check Wirings			\$ 40.00
TOTAL LABOUR				\$ 740.00
ESTIMATE TOTAL				\$ 4,037.08

de -
 net -
 sub -
 ab -
 X }
 X }
 X }
 sub
 1333.55
 1066.84
 350
 250
 X }
 600
 1666.84
 4037.08
 2 days

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanjin 97475749
 WP' 4/8/22 @ 450pm
 2 days
 4/13 rising after repair
 tanjin e llhants...

Auto Consultants hence notify the Repairer of the following:

- Resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

As acknowledged by Repairer
 Signature: