

CITYCAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHB4751J

02.08.2022

MAKE REG: 05.01.2017

MODEL HYU- I40

Type

CHIANG/ NTUC

Qty	Parts Description/ Labour	Unit Price	Amount
1	REAR BUMPER COVER		\$553.00
1	REAR BUMPER LOWER COVER		\$228.00
1	REAR BUMPER REINFORCEMENT		\$428.40
10	REAR BUMPER CLIPS	\$2.20	\$22.00
2	REAR BUMPER BRACKET LH/RH	\$35.60	\$71.20
2	REAR BUMPER REFLECTOR LH/RH	\$32.00	\$64.00
	SUB TOTAL		\$1,366.60
	20.00%		\$273.32
	DISCOUNTED TOTAL		\$1,093.28
1	REAR BUMPER ADVERTISEMENT		\$50.00
2	REAR FENDER ADVERTTISEMENT	\$100.00	\$200.00
1	REAR BUMPER MAT		\$50.00
1	REAR REVERSE SENSOR		\$135.70
			\$372.13
	Labour Charge		
	Panel Beating		\$450.00
	Spray Painting Charge		\$300.00
	Remove/refix reverse sensor		\$60.00
	Check Lighting & Wiring		\$40.00
	TOTAL LABOUR		\$850.00
	ESTIMATE TOTAL		\$2,315.41
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

Tan Jiah 97495749
 WP 3/8/22 4 PM
 02 days
 do this after repair
 tan jiah @ hband

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: