

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

DATE: 04.08.2022

MODEL: Hyundai Ioniq

VEHICLE NO.: SHD6505E

INSURANCE: NTUC (4S)

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Front Bumper	1		\$ 481.10
	Front Bumper Clips	10	\$ 2.20	\$ 22.00
	Front Bumper Upper Moulding	1		\$ 368.50
	Frt Fender Shield RH	1		\$ 588.80
	Frt Wheel Cap RH	1		\$ 346.40
	Headlamp RH	1		\$ 2,110.30
	DayLight RH	1		\$ 642.50
	DayLight Grille RH	1		\$ 93.45
	SUB TOTAL			\$ 4,653.05
	LESS 20%			\$ 930.61
	TOTAL SPARE PARTS			\$ 3,722.44
	Front WestLake Tyre RH	1	60%	\$ 216.00
	Labour Charge			
	Panel Beating			\$ 400.00
	Spray Painting			\$ 600.00
	Check Wirings			\$ 40.00
	Wheel Alignment			\$ 120.00
	TOTAL LABOUR			\$ 1,160.00
	ESTIMATE TOTAL			\$ 5,098.44

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanji 92495749
 - WP #10720420
 62 days
 1/3 rising after repair
 Tanji @ 11:00 am