

ASS. REC. BY: Taught

REF:

INC

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
	<input checked="" type="checkbox"/>

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHD3030C Yr Regn: 2022 JulyType: M.Car / M.Cycle / Bus / Van / Lorry (Taxi) / Prime Mover /

Truck / Trailer or

Make: Toyota Prius C.C. 1798Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 819 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: STDKR3FU* 403096907Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: NI / S/Rim / STD A/Rim orTyre Size: F: 195/65R5R: 2

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Winstar

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 01/08/22Survey held at Confident Logics

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP - INC - SJR 2878 H

Date/Time, File Pass 10?

☐ : Preli. Report

1) _____

☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Rep. Format: _____

Lump Sum / L.S. (\$) _____

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Vehicle No.: SHD3030
Make : TOYOTA
Model : PRIUS G4
DOA : 30.07.2022

Date : REG 28.07.2022
Insurance: NTUC
MVA : CHIANG
Admin :

Part No.	Parts Description / Labour	Qty	Unit Price	Amount
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE			Ry \$1,054.71
1	REAR TRUNK LID LOGO (PRIUS)			na \$60.80
1	REAR TRUNK LID LOGO (HYBRID)			na \$52.40
1	REAR TRUNK LID LOGO (TOYOTA STAR)			x \$52.90
1	REAR TRUNK LID LOCK			X \$530.79
1	TRANSMITTER,ELETRICAL KEY			x \$447.10
1	REAR BUMPER			de \$503.04
1	REAR BUMPER UNDER COVER			de \$654.96
1	REAR BUMPER REINFORCEMENT			? \$378.32
2	REAR BUMPER SIDE RETAINER LH/RH	LHX	\$112.70	RH de \$225.40
1	REAR BUMPER UNDER COVER CENTRE			X \$252.00
1	REAR BUMPER TOWING COVER			de \$82.70
1	REAR BUMPER REFLECTOR LH/RH		\$55.00	X \$110.00
1	REAR END PANEL			X \$738.96
1	REAR END PANEL GARNISH			X \$165.80
10	REAR BUMPER CLIPS			x \$22.00
	SUB TOTAL			\$5,331.88
	LESS 25%			\$1,332.97
	DISCOUNTED TOTAL			\$3,998.91
1	REAR TRUNK LID APPS STICKER			na \$40.00
1	REAR TRUNK LID COMFORT & TEL NO. STICKER		\$30.00	na \$60.00
1	REAR BUMPER MAT			na \$50.00
1	REAR NUMBER PLATE W/HOLDER			X \$50.00
1	REAR BUMPER REVERSE SENSOR			? \$135.70
		10.00%		\$307.13
	Labour Charge			
	Panel Beating			350 \$1,050.00
	Spray Painting Charge			500 \$600.00
	Wiring Charge			X \$60.00
	Tuff Kote			X \$90.00
	Towing Fee			X \$60.00
	Remove/Refix Reverse Sensor			50 \$60.00
	TOTAL LABOUR			\$1,920.00
	ESTIMATE TOTAL			\$5,918.91

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: **TOTAL LABOUR**

Tanfer 92495749
w/ 1/8/22 e 330pm
2 days

R/P Resurvey before paint
tanfer@lkkauto.com

Date/Time: 01.08.2022 12:53

Page : 1

Job: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 4493661

JC No: 805525033

Customer: COMFORT TRANSPORTATION PTE LTD
Customer No: 7010045
Address: 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)

Count Card No.

REGN NO.: SHD3030C

MILEAGE

MAKE: TOYOTA

FUEL

E.....1/2.....F

MODEL: PRIUS HYBRID(G4A01.08.2022 09:55

DATE/TIME IN

YR OF MANU: 28.07.2022

TARGET DATE


CHASSIS CODE: JTDKB3FU403096907

COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 30.07.2022
Nature: 3P 30.07.2022

NO LABOR CODE DESCRIPTION



Checked & Passed Out By:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Wedge Slip

Exit Pass

No.: SHD3030C

CHIANG

Vehicle No.: SHD3030C

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard