

FORTDELGRO ENGINEERING PTE LTD

PAIR ESTIMATE*

VEHICLE NO SHD4324Z

DATE 03.08.2022

MAKE/REG 25.10.2019

CHIANG/NTUC

MODEL : HYUNDAI IONIQ G2

Qty	Parts Description/ Labour	Type	Amount
1	FRONT BUMPER		\$481.10
1	LH SIDE ROCKER GARNISH		\$290.00
1	FRONT DOOR LH		\$1,797.20
1	FRONT DOOR MOULDING LH		\$110.10
1	REAR DOOR LH		\$1,789.90
1	REAR DOOR MOULDING LH		\$125.30
2	WHEEL CAP LH		\$692.80
	SUB TOTAL		\$5,286.40
	LESS 20%		\$1,057.28
	DISCOUNTED TOTAL		\$4,229.12
1	REAR DOOR COMFORT APP		\$80.00
1	REAR FENDER ADVERTISEMENT		\$100.00
1	REAR DOOR ADVERTISEMENT		\$100.00
1	FRONT FENDER ADVERTISEMENT		\$100.00
1	FRONT DOOR ADVERTISEMENT		\$100.00
1	FRONT DOOR COMFORT STICKER		\$75.00
	Labour Charge		
	Panel Beating		\$1,050.00
	Spray Painting Charge		\$1,300.00
	Remove/Refix rear upholstery		\$90.00
	Remove/refix door parts		\$180.00
	Check Wiring		\$60.00
	TOTAL LABOUR		\$2,680.00
	ESTIMATE TOTAL		\$7,448.62

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanphat 97415749

4/8/22 @ 430pm

L/S Mary after repair

Tanphat@lkkauto.com

03 days