

ASS. REC. BY: Taughn

REF:

CTI

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
	X

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: SUA 5984C Yr Regn: 2016, DEC.
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota Prius C.C. 1798
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 402411 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JTDKB3FP9403539430
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: NI / S/Rim / STD A/Rim or _____
 Tyre Size: F: 195/65R15
 R: ~ ~
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Wentlake
 Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 01/08/22
 Survey held at Compt Luyen
 Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop: or _____

The U/C / Chassis frame / Body Structure affected due to collision.

TP - CTI - SMR71035

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1) _____
 Date/Time, File Return to?

☐ : Final Report

Resurvey No. of Trip: _____

2) _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

____ S + RS. ____ SI

Photos

Others

TOTAL

Rep. Format: _____

Lump Sum / L.B.R. (%) _____

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Vehicle No.: SHA5984C
 Make : TOYOTA
 Model : PRIUS G4
 DOA : 30.07.2022

Date : REG 23.12.2016
 Insurance: CHINA
 MVA : CHIANG
 Admin :

Part No.	Parts Description / Labour	Qty	Unit Price	Amount
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE			Ry \$1,054.71
1	REAR TRUNK LID LOGO (PRIUS)			ner \$60.80
1	REAR TRUNK LID LOGO (HYBRID)			ner \$52.40
1	REAR TRUNK LID LOGO (TOYOTA STAR)			x \$52.90
1	TRANSMITTER, ELETRICAL KEY			R \$447.10
1	REAR BUMPER			de \$503.04
1	REAR BUMPER UNDER COVER			x \$654.96
1	REAR BUMPER REINFORCEMENT			? \$378.32
2	REAR BUMPER SIDE RETAINER LH/RH		\$112.70	? \$225.40
1	REAR BUMPER TOWING COVER			de \$82.70
1	REAR BUMPER REFLECTOR LH/RH		\$55.00	x \$110.00
1	REAR END PANEL			x \$738.96
1	REAR END PANEL GARNISH			x \$165.80
10	REAR BUMPER CLIPS			ner \$22.00
	SUB TOTAL			\$4,549.09
	LESS 25%			\$1,137.27
	DISCOUNTED TOTAL			\$3,411.82
1	REAR BUMPER ADVERTISEMENT			art \$50.00
2	REAR FENDER ADVERTISEMENT		\$100.00	ner \$200.00
1	REAR TRUNK LID APPS STICKER			ner \$40.00
1	REAR TRUNK LID COMFORT & TEL NO. STICKER		\$30.00	ner \$60.00
1	REAR NUMBER PLATE W/HOLDER			x \$55.00
1	REAR BUMPER REVERSE SENSOR			ner \$135.70
		10.00%		\$540.70
	Labour Charge			
	Panel Beating			350 \$1,050.00
	Spray Painting Charge			500 \$600.00
	Wiring Charge			x \$60.00
	Tuff Kote			x \$90.00
	Towing Fee			lowing except? \$60.00
	Remove/Refix Reverse Sensor			30 \$60.00
	TOTAL LABOUR			\$1,920.00
	ESTIMATE TOTAL			\$5,872.52

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

tanpin @lharts.com

Date/Time: 01.08.2022 12:55

Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4493727

JC NO: 505525034

STOMER

/MS COMFORT TRANSPORTATION PTE LTD

STOMER NO. 7010045

DRESS 383 SIN MING DRIVE

Singapore SINGAPORE 575717

.. (R) 65508755

(O)

(P)

COUNT CARD NO.

REGN NO.:

SHA5984C

MILEAGE

MAKE:

TOYOTA

FUEL

E.....1/2.....F

MODEL

PRIUS HYBRID(G4)01.08.2022 09:35

DATE/TIME IN

YR OF MANU.

23.12.2016

TARGET DATE

CHASSIS CODE

JTDKB3FU403539430

COMPLETION DATE/TIME:


JOB DESCRIPTION

Accident Date: 30.07.2022

ATURE: 3P 30.07.2022

NO LABOR CODE

DESCRIPTION



CKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

lo.: SHA5984C

CHIANG

Vehicle No.:

SHA5984C

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard