

Premium Automobiles

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

1/9/22 wip: 35657

Bend.



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKV 939 X

AIG - Admin
- 3 days

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Repis</i>	1	\$ 2,377.00	+
2	FRONT BUMPER FIXING PARTS <i>3 new</i>	1	\$ 612.00	+
3	FRONT BUMPER SECURING STRIP	2	\$ 79.00	+
4	FRONT BUMPER LOWER GRILLE - CENTER <i>new</i>	1	\$ 219.00	+
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	1	\$ 254.00	+
6	FRONT RADIATOR AIR GUIDE - LH / RH <i>new</i>	2	\$ 144.00	+
7	RADIATOR GRILLE <i>cracked</i>	1	\$ 1,478.00	✓
8	RADIATOR AIR GUIDE GRILLE - LH / RH <i>new</i>	2	\$ 302.00	+
9	FRONT BUMPER FOAM FILLER PIECE <i>cracked</i>	1	\$ 139.00	✓ <i>3 H.S.</i>
10	FRONT BUMPER CARRIER <i>new</i>	1	\$ 899.00	✓ <i>3 H.S.</i>
11	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	2	\$ 82.00	+
12	FRONT BUMPER TOP COVER <i>new</i>	1	\$ 143.00	+
13	CAUTION SIGN STICKER <i>3 new</i>	1	\$ 16.00	+
14	AIR CONDITIONER STICKER	1	\$ 9.00	+
15	FRONT BUMPER BRACKET	1	\$ 154.00	+
16	FRONT BUMPER SUPPORT <i>new</i>	1	\$ 64.00	✓ <i>3 H.S.</i>
17	POP RIVET <i>new</i>	4	\$ 4.00	✓ <i>3 H.S.</i>
18	FRONT PARKING AID SENSOR - INNER / OUTER <i>1 piece missing</i>	2	\$ 531.00	265 SD
19	FRONT BUMPER PARKING AID SEAL RING <i>new</i>	4	\$ 10.00	+
20	FRONT BUMPER WIRING SET <i>new</i>	1	\$ 567.00	+
SUB TOTAL SPARE PARTS		:	\$ 8,083.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

Admin
H.S.