

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0649/2022/EQ
DATE : 2-Aug-22
WIP : 35657

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 8/8/2022.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

3 days - ok - Johnny Boo

29-Nov-22

OWNER'S NAME : MR. MAK KIAN SOON BENJAMIN
ADDRESS : 45 PASIR PANJANG HILL
#04-14
SINGAPORE 118864
TELEPHONE : HP +65 98397242
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800143872-02
VEHICLE NO : **SKV 939 X**
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI
MODEL YEAR : 20/12/2018
ENGINE NO : CVK 071541
CHASSIS NO : WAUZZZF46KN000633
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 1-Aug-22
PLACE OF ACCIDENT : ALONG SCIENCE PARK DRIVE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKV 939 X

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$ 480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	700.00	
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. TO REPAIR BONNET. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,400.00	\$ 500.00
4	TO RESPRAY FRONT BUMPER AND BONNET.	\$	2,000.00	\$ 550.00
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$	4,772.00	\$ 1,722.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKV 939 X

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,377.00	
2	FRONT BUMPER FIXING PARTS	1	\$ 612.00	
3	FRONT BUMPER SECURING STRIP	2	\$ 79.00	
4	FRONT BUMPER LOWER GRILLE - CENTER	1	\$ 219.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 254.00	
6	FRONT RADIATOR AIR GUIDE - LH / RH	2	\$ 144.00	
7	RADIATOR GRILLE	1	\$ 1,478.00	\$ 1,182.40
8	RADIATOR AIR GUIDE GRILLE - LH / RH	2	\$ 302.00	
9	FRONT BUMPER FOAM FILLER PIECE	1	\$ 139.00	\$ 110.80
10	FRONT BUMPER CARRIER	1	\$ 899.00	\$ 719.20
11	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 82.00	
12	FRONT BUMPER TOP COVER	1	\$ 143.00	
13	CAUTION SIGN STICKER	1	\$ 16.00	
14	AIR CONDITIONER STICKER	1	\$ 9.00	
15	FRONT BUMPER BRACKET	1	\$ 154.00	
16	FRONT BUMPER SUPPORT	2	\$ 64.00	\$ 25.60
17	POP RIVET	4	\$ 4.00	\$ 2.88
18	FRONT PARKING AID SENSOR - INNER / OUTER	2	\$ 531.00	\$ 212.00
19	FRONT BUMPER PARKING AID SEAL RING	4	\$ 10.00	
20	FRONT BUMPER WIRING SET	1	\$ 567.00	
SUB TOTAL SPARE PARTS		:	\$ 8,083.00	\$ 2,252.88

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKV 939 X

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		<i>\$ 2,252.88</i>
21	HORN HIGH TONE - LH	1	\$ 134.00	
22	HORN LOW TONE - RH	1	\$ 139.00	
23	HORN BRACKET - LH / RH	2	\$ 66.00	
24	HEADLIGHT - LH / RH	2	\$ 16,588.00	
25	LIFT CYLINDER - LH / RH	2	\$ 462.00	
26	LIFT CYLINDER BRACKET	2	\$ 14.00	
27	LIFT CYLINDER HOSE	1	\$ 107.00	
28	FRONT RADIATOR AIR GUIDE - LH / RH	2	\$ 64.00	
29	FRONT RADIATOR AIR GUIDE - LH / RH	2	\$ 28.00	
30	RADIATOR AIR GUIDE - UPPER	1	\$ 19.00	
31	FRONT NO PLATE	S/N	\$ 60.00	<i>\$ 60.00</i>
32	SUPPLEMENTARY		<i>\$ 21.00</i>	<i>\$ 16.32</i>
33	SUNDRIES		\$ 350.00	
TOTAL SPARE PARTS			\$ 26,135.00	\$ 2,329.20
TOTAL LABOUR CHARGES			\$ 4,772.00	\$ 1,722.00
GRAND TOTAL			\$ 30,907.00	\$ 4,051.20

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-29/11/22



PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0649/2022/EQ 19-Oct-22 CHANG 1 of 1 SKV 939 X AUDI A4 SEDAN 2.0 TFSI	
Quantity	Description		Unit Price	Amount
<u>Parts</u>				
1	OUTER TEMP. SENSOR BRACKET	1	\$ 21.00	\$ 16.32
	GRAND TOTAL		\$ 21.00	\$ 16.32

For Premium Automobiles Pte Ltd

Authorised Signature



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT