

CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

DA/III(SNC7652R)

DOA: 28/07/2022@1400

INDIA INTERNATIONAL INSURANCE PTE LTD

02/08/2022

ATTN: THE MOTOR CLAIM DEPT


THIRD PARTY CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:

SMF 3151 S - KIA CERATO 1.6(A) SX

CHASSIS NO: KNAF3416MK5019051 (2018)

1 pc	Bonnet	\$	944.00
1 pc	Bonnet sponge	\$	136.00
13 pcs	Bonnet sponge clips @ \$3.50	\$	45.50
1 pc	Bonnet hinge LHS	\$	55.00
1 pc	Bonnet hinge RHS	\$	55.00
1 pc	Bonnet lock	\$	80.00
1 pc	Front bumper	\$	468.00
1 pc	Front bumper logo	\$	35.00
1 pc	Front bumper grille (TOP)	\$	220.00
1 pc	Front bumper grille chrome	\$	125.00
1 pc	Front bumper towing cover	\$	35.00
1 pc	Front bumper signal LHS	\$	185.00
1 pc	Front bumper signal RHS	\$	185.00
1 pc	Front bumper signal lamp socket LHS	TBC	
1 pc	Front bumper foglight RHS	\$	245.00
1 pc	Front bumper foglight cover LHS	\$	80.00
1 pc	Front bumper foglight cover RHS	\$	80.00
1 pc	Front bumper side grille LHS	\$	180.00
1 pc	Front bumper side grille RHS	\$	180.00
1 pc	Front bumper lower center grille	\$	360.00
1 pc	Front bumper lower center grille parking sensor LHS	\$	160.00
1 pc	Front bumper lower center grille parking sensor RHS	\$	160.00
1 pc	Front bumper lower spoiler	TBC	
1 pc	Front bumper lower seal	\$	70.00
1 pc	Front bumper under cover	\$	160.00
8 pcs	Front bumper under cover clips @ \$3.50	\$	28.00
10 pcs	Front bumper clips @ \$3.50	\$	35.00
1 pc	Front bumper sponge	\$	135.00
1 pc	Front bumper reinforcement	\$	355.00
1 pc	Front bumper foglight bulb RHS	\$	15.00
1 pc	Front bumper top garnish	\$	65.00
1 pc	Front bumper lower beam	\$	135.00



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

SMF 3151 S - KIA CERATO 1.6(A) SX

1 pc	Parking sensor wire harness	\$ 185.00
1 pc	Headlamp LHS	\$ 1,450.00
1 pc	Headlamp RHS	\$ 1,450.00
1 pc	A/C condenser	\$ 780.00
1 pc	A/C outer tempt sensor	\$ 70.00
1 pc	Radiator	\$ 550.00
1 pc	Radiator fan motor assy	\$ 450.00
1 pc	Radiator top hose	\$ 35.00
1 pc	Radiator top hose joint	\$ 135.00
1 pc	Radiator side garnish LHS	\$ 35.00
1 pc	Radiator side garnish RHS	\$ 35.00
1 pc	Air duct	\$ 80.00
1 pc	Air filter lower casing	\$ 105.00
1 pc	Battery under tray	\$ 85.00
1 pc	Support panel	\$ 550.00
1 pc	Throttle body	\$ 780.00
		\$ 11,786.50
	LESS 10%	\$ 1,178.65
		\$ 10,607.85
1 pc	Front no.plate (S/NETT)	\$ 35.00
1 pc	Radiator Coolant (S/NETT)	\$ 35.00
1 set	Body Sticker (S/NETT)	\$ 650.00
	Remove, replace a/c condenser & fittings inclusive refill gas	\$ 100.00
	Check wiring function	\$ 40.00
	Remove necessary parts: jacking, panel beating, repair and straighten front inner panel, front fenders LHS/RHS inclusive replacing the above.	\$ 880.00
	Putty and respray front support panel, front bonnet, front fenders LHS/RHS, front bumper and affected areas.	\$ 800.00
		\$ 13,147.85
	ADD 7% GST	\$ 920.35
		\$ 14,068.20

Note: The above is an estimate only. IF other parts requested during the course of repair, we will inform you accordingly.

All parts are subject to availability.

Page 2 of 2

CHARN'S CUSTOMCRAFT

.....