



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2300359

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 17/01/2023
Reference CC6/CTI22007582/Upa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SMP 7403L
Insured Veh. SJA 5606X
Claim No. SNM22D205570
Policy No. DMHCSNW00000102201
Accident Date 02/08/2022
Inspection Date 10/08/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22007582/Upa3q2 Date: 17/01/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJA 5606X	Veh. Inspected	SMP 7403L	
Policy No.	DMHCSNW00000102201	Coverage (\$)	0.00	
Claim No.	SNM22D205570	Excess (\$)	0.00	
Assign From		Assign Date	10/08/2022	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ B 200 (A)	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	WDD2462432J142096	Colour	GREY	
Odometer	132159 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	CONTINENTAL	6 mm	
L/H Front Tyre	205/55 R16	CONTINENTAL	6 mm	
R/H Rear Tyre	205/55 R16	CONTINENTAL	6 mm	
L/H Rear Tyre	205/55 R16	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/08/2022	Inspection Date	10/08/2022	
Survey held at	SOON SAN MOTOR TRADING BLK 3006 UBI ROAD 1 #01-390 SINGAPORE 408716			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMP 7403L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAIL GATE	BADLY DENTED	2,123.00	2,005.32
1	TAIL GATE B200 PLATE	NECESSARY	88.00	88.00
1	TAIL GATE CC PLATE	NECESSARY	18.00	18.00
1	TAIL GATE EMBLEM	NECESSARY	60.00	60.00
1	TAIL GATE CENTRE CHROME	NOT NECESSARY	350.00	-
1	TAIL GATE TOP LOCK	NOT NECESSARY	65.00	-
1	TAIL GATE LOWER LOCK	NOT NECESSARY	245.00	-
2	TAIL GATE REFLECTORS @\$475.00	NOT NECESSARY	950.00	-
1	TAIL GATE RUBBER	TORN	220.00	220.00
1	TAIL GATE LOCK SWITCH CENTRE	NOT NECESSARY	180.00	-
1	TAIL GATE WINDSCREEN MOULDING	NECESSARY	98.00	98.00
1	REAR PANEL	TO REPAIR SEE LABOUR	850.00	-
1	REAR PANEL LOWER LOCK COVER	NOT NECESSARY	128.00	-
1	REAR BUMPER	DISTORTED	1,670.00	1,415.22
1	REAR BUMPER TOP CHROME	MISSING	300.00	300.00
3	REAR BUMPER REVERSE SENSORS @\$316.00	SHORTED (2 PCS ONLY)	948.00	360.00
1	REAR BUMPER LOWER SPOILER	DISTORTED	280.00	280.00
10	REAR BUMPER LOWER SPOILER CLIPS @\$10.00	NOT NECESSARY	100.00	-
2	REAR BUMPER SIDE HOLDERS @\$90.00	BENT	180.00	180.00
1	REAR BUMPER REINFORCEMENT	DENTED	390.00	390.00
2	REAR BUMPER SIDE MOULDING @\$152.00	NECESSARY	304.00	304.00
1	REAR EXHAUST PIPE TOP HEAT COVER	BENT	203.00	203.00
	LESS 10% DISCOUNT		-975.00	-592.15
			8,775.00	5,329.39
1	TAIL GATE WINDSCREEN INNER SEALANT (SN)	NECESSARY	140.00	40.00
1	SET TAIL GATE TAPE FOAM (SN)	NECESSARY	65.00	40.00
1	SET REAR BUMPER INNER CLIPS (SN)	NECESSARY	100.00	50.00

Report Ref No. CC6/CTI22007582/Upa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-30.50	-
			274.50	130.00
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE WITH COVER (SN)	NOT NECESSARY	100.00	-
			100.00	-
	<u>LABOUR</u>			
	TO RUSTPROOF .		200.00	40.00
	TO REMOVE/REFIT REAR WINDSCREEN .		140.00	120.00
	TO DISMANTLE /RENEW TAIL GATE .		150.00	60.00
	TO CHECK WIRING .		50.00	20.00
	TO RESET COMPUTER .	NOT NECESSARY	100.00	-
	TO REMOVE/REFIT REAR INTERIOR TO EFFECT REPAIR .		100.00	80.00
	TO DISMANTLE /RENEW REVERSE SENSORS.		100.00	50.00
	TO REMOVE /REFIT TOP SPOILER .	NOT NECESSARY	100.00	-
	TO DISMANTLE /RENEW ACCIDENT PORTION .INCLUSIVE OF THE REPAIR OF REAR PANEL .		1,500.00	600.00
	TO SPRAY PAINT.		1,500.00	800.00
			3,940.00	1,770.00
GRAND TOTAL			13,089.50	7,229.39
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,300.00

Report Ref No. CC6/CTI22007582/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMP 7403L

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMP 7403L

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

