

(08/11/13) wef

ASS. REC. BY: *Marcus*REF: *CC6/C 7/22007582/Uga3***ASSIGNMENT**

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Date / Time

Action / Instruction

*Bot Smith.**coe unel 27-03-2023 LTA 612685**Exp 16k. Net 2535**16/08/22 2/s #5300 informed Vincent.*

Veh No:

SMP 7403L

Yr Regn:

*28/03/13*Type: *M.Car* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA/

Make:

Mer Benz B200 c.c. *1595*

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading:

132/59

T/Radio: Insured / Std / NI / NA

Eng/No:

WDD2462432J142096

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

205/55-R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

*Continental**6**6**02/08/22**1**Rear**Rear**6**6**10/08/22**1**1**1**1**1**1**1**1**1**1**1**1**1**1**1**1**1**1**1*

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

) \$ + RS \$

) Photos

) Others

TOTAL

Report Format:

Lump Sum / I.B.I: (\$

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

CHINA TAIPING INSURANCE (S) PTE LTD

3, Anson Rd #16-00

Springleaf Tower

S,pore 079909

Date accident :02/08/2022

Date: 03/08/2022

Not Authorized
Lian Moray
10/8/22
2/5 # S3001
4 days.
Zhe zhe Affix

Limited Repair

Estimate cost to repair vel: SMP 7403L (Mercedes B200) claims under vel: SJA 5606X.

1pce tail gate	2005-32	\$ 2,123.00	3odlyad ✓
1pce tail gate B200 plate		88.00	1er ✓
1pce tail gate cc plate		18.00	1er ✓
1pce tail gate emblem		60.00	1er ✓
1pce tail gate centre chrome		350.00	11 X
1pce tail gate top lock		65.00	11 X
1pce tail gate lower lock		245.00	11 X
2pcs tail gate reflectors @\$475		950.00	11 X
1pce tail gate rubber		220.00	Torn ✓
1pce tail gate lock switch centre		180.00	11 X
1pce tail gate windscreen inner sealant		140.00	1er 40 S/N
1set tail gate tape form		65.00	1er 40 S/N
1pce tail gate windscreen outer rubber moulding		98.00	1er ✓
1pce rear panel		850.00	R X
1pce rear panel lower lock cover		128.00	11 X
1pce rear bumper	1415-22	1,670.00	715 ✓
1pce rear bumper top chrome		300.00	715 ✓
3pcs rear bumper reverse sensors@\$316	1642-360	948.00	shard 2 pcs
1pce rear bumper lower spoiler		280.00	715 ✓
10pcs rear bumper lower spoiler clips@\$10		100.00	11 X
10pcs rear bumper inner clips@\$10		100.00	1er 50 S/N
2pcs rear bumper side holders@\$90		180.00	Bent ✓
1pce rear bumper reinforcement		390.00	715 ✓
2pcs rear bumper side mouldings@\$152		304.00	1er ✓
1pce rear exhaust pipe top heat cover		203.00	Bent ✓
Page 1			

1set

(102)

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

CHINA TAIPING INSURANCE (S) PTE LTD

3, Anson Rd #16-00

Springleaf Tower

S,pore 079909

Date accident :02/08/2022

Date: 03/08/2022

Estimate cost to repair vel: SMP 7403L (Mercedes B200) claims under vel: SJA 5606X.

[illegible]

Date:

P-5821.54
102

5329.38
130
1770

7229.38
5183