| 7 | FASTECH AUTO PTE LTD | duk |
|------|---|---------------|
| | 1 Kaki Bukit Ave 6 #01-48 Autobay | 1-1-12 |
| | Singapore 417883 | 1018/11 |
| | Tel No: 67452063/ 67467158 Fax No: 67458520 | 11 |
| | Tax Reg No : 200006262D | 7/5\$ 18:00 |
| | VEHICLE No: SJJ 1176Z | 15-day |
| 1PC | BOOTLID | \$966.10 × |
| 1PC | BOOTLID REAR LOGO | \$68.50 × |
| 1PC | BOOTLID 'COROLLA' EMBLEM 1 | \$62.80 🗶 |
| 1PC | BOOTLID 'ALTIS' EMBLEM | \$58.00 × |
| 1PC | BOOTLID INNER LOCK | \$409.10 X |
| 1PC | BOOTLID LOCK STRICKER MA | \$66.80 × |
| 1PC | BOOTLID WEATHERSTRIP 1 | \$282.30 X |
| 2PCS | BOOTLID REFLECTORS @\$310.90 MS (re | \$621.80 126 |
| 1PC | BOOTLID INNER TRIM | \$366.10 |
| 1PC | BOOTLID OUTER CHROME GARNISH | \$311.80 |
| 2PCS | BOOTLID HINGES @\$165.00 | \$330.00 🔀 |
| 1PC | REAR BUMPER DIS | \$655.10 |
| 1PC | REAR BUMPER BEAM | \$395.40 |
| 2PCS | REAR BUMPER REFLECTORS @\$60.00 \(\sigma \) \(\sigma \) | \$120.00 176 |
| 2PCS | REAR BUMPER SIDE RETAINERS @\$65.00 Buf (cm | \$130.00 |
| 1SET | REAR BUMPER CLIPS | \$50.00 |
| 1PC | REAR END PANEL Beds 100 | \$788.20 |
| 1PC | REAR END PANEL TOP GARNISH | \$362.30 🗶 |
| 2PCS | TAILLAMPS @\$680.00 MS BND 435110 | \$1,360.00 60 |
| 2PCS | TAILLAMP LOWER BRACKETS @\$65.00 | \$130.00 120 |
| 2PCS | TAILLAMP HOUSING PANELS @\$425.00 MS DUS | \$850.00 (2) |
| 1PC | REAR ANTENNA SENSOR | \$241.20 🗶 |
| 1PC | REAR FLOOR PANEL | \$1,145.20 🔀 |
| 1PC | REAR FLOOR PANEL TOP BOARD 7000 340.10 | \$620.50 |
| 1PC | REAR FLOOR PANEL SIDE N/S MEMBER | \$366.10 |
| 2PCS | REAR FENDERS @\$945.10 | \$1,890.20 12 |
| 2PCS | REAR FENDER INNER TRIMS @\$281.10 | \$562.20 🗶 |
| 1PC | REAR FENDER SPLASH SHIELD N/S | \$68.10 |
| 1PC | REAR AIR VENT N/S | \$45.00 |
| 1PC | REAR EXHAUST | \$899.10 🗴 |
| 1PC | REAR EXHAUST HEAT SHIELD | \$122.10 × |
| 1PC | REAR EXHAUST MOUNTING | \$45.00 🗶 |
| 1PC | REAR SPARE TYRE LOCK NUT | \$55.10 🗶 |
| 1PC | REAR WINDSCREEN | \$1,085.20 🗶 |
| 1PC | REAR WINDSCREEN MOULDING 1.11 | \$118.00 |
| 1PC | REAR DOOR N/S | \$1,108.10 X |
| 1PC | REAR DOOR INNER LOCK N/S | \$425.00 × |
| 1PC | REAR WHEEL HOUSING PANEL N/S | \$899.10 × |
| 1PC | REAR FUEL TANK | \$1,285.00 > |
| 1PC | REAR SHOCK ABSORBER N/S | \$298.00 × |
| 1PC | REAR WHHEL HUB BEARING N/S | \$485.00 |
| 1PC | REAR AXLE BEAM | \$3,410.00 🗡 |
| | | |

Not Authorist

| V | FASTECH AUTO PTE LTD | disk |
|------------|--|----------------|
| | 1 Kaki Bukit Ave 6 #01-48 Autobay | 1 1 |
| | Singapore 417883 | 10/8/2 |
| | Tel No: 67452063/ 67467158 Fax No: 67458520 | |
| | Tax Reg No : 200006262D | L/(# 18000 |
| | 147.1105.110.1.200002020 | 3 10 1000 |
| | VEHICLE No: SJJ 1176Z | 15 Long |
| | 7 2 110 2 110 1 0 3 2 2 7 0 2 | , [] |
| 1PC | BOOTLID | \$966.10 × |
| 1PC | BOOTLID REAR LOGO | \$68.50 × |
| 1PC | BOOTLID 'COROLLA' EMBLEM 1 | \$62.80 / |
| 1PC | BOOTLID 'ALTIS' EMBLEM // | \$58.00 🗸 |
| 1PC | BOOTLID INNER LOCK ^^ | \$409.10 X |
| 1PC | BOOTLID LOCK STRICKER M | \$66.80 🗴 |
| 1PC | BOOTLID WEATHERSTRIP 1 | \$282.30 X |
| 2PCS | BOOTLID REFLECTORS @\$310.90 MS (re | \$621.80 126 |
| 1PC | BOOTLID INNER TRIM | \$366.10 |
| 1PC | BOOTLID OUTER CHROME GARNISH 🗸 🔨 | \$311.80 🔾 |
| 2PCS | BOOTLID HINGES @\$165.00 | \$330.00 × |
| 1PC | REAR BUMPER DIS | \$655.10 |
| 1PC | REAR BUMPER BEAM | \$395.40 |
| 2PCS | REAR BUMPER REFLECTORS @\$60.00 NS CAL | \$120.00 176 |
| 2PCS | REAR BUMPER SIDE RETAINERS @\$65.00 But (cm | \$130.00 |
| 1SET | REAR BUMPER CLIPS New | \$50.00 |
| 1PC | REAR END PANEL Sols M | \$788.20 |
| 1PC | REAR END PANEL TOP GARNISH | \$362.30 🗶 |
| 2PCS | TAILLAMPS @\$680.00 MS 120 435110 | \$1,360.00 (2) |
| 2PCS | TAILLAMP LOWER BRACKETS @\$65.00 | \$130.00 120 |
| 2PCS | TAILLAMP HOUSING PANELS @\$425.00 MS DIS | \$850.00 (2) |
| 1PC | REAR ANTENNA SENSOR | \$241.20 🗶 |
| 1PC | REAR FLOOR PANEL | \$1,145.20 × |
| 1PC | REAR FLOOR PANEL TOP BOARD 7000 340.10 | \$620.50 |
| 1PC | REAR FLOOR PANEL SIDE N/S MEMBER | \$366.10 X |
| 2PCS | REAR FENDERS @\$945.10 M(s') | \$1,890.20 12 |
| 2PCS | REAR FENDER INNER TRIMS @\$281.10 | \$562.20 🗶 |
| 1PC | REAR FENDER SPLASH SHIELD N/S | \$68.10 |
| 1PC | REAR AIR VENT N/S | \$45.00 |
| 1PC | REAR MHAUST | \$899.10 × |
| 1PC | REAR EXHAUST HEAT SHIELD | \$122.10 × |
| 1PC | REAR EXHAUST MOUNTING REAR SPARE TYRE LOCK NUT | \$45.00 × |
| 1PC | | \$55.10 🗶 |
| 1PC 1PC | | \$1,085.20 × |
| | REAR WINDSCREEN MOULDING AM REAR DOOR N/S | \$118.00 |
| 1PC 1PC | REAR DOOR INNER LOCK N/S | \$1,108.10 × |
| 1PC | REAR DOOR INNER LOCK N/S REAR WHEEL HOUSING PANEL N/S | \$425.00 × |
| 1PC | REAR WHEEL HOUSING PANEL N/S REAR FUEL TANK | \$899.10 × |
| 1PC | REAR SHOCK ABSORBER N/S | \$1,285.00 × |
| 1PC | REAR WHHEL HUB BEARING N/S | \$298.00 × |
| 1PC | | \$485.00 |
| 110 | REAR AXLE BEAM | \$3,410.00 |

Not Authorist

| 2 | | |
|-----|--|--------------------------------|
| 1PC | REAR TYRE N/S Par | \$50.00 40 \$200.00 SVZ 100 |
| 1PC | REAR SPORT RIM N/S | \$400.00 |
| | 201 | \$400.00 |
| 1PC | FRONT SPORT RIM N/S | \$200.00 (02/0) |
| 1PC | FRONT TYRE N/S | \$200.00 506 100 |
| | | |
| | TO CHECK WIRING | \$50.00 30 |
| | TO DISMANTLE & REPLACED REVERSE SENSOR | \$80.00 (~) |
| | TO DISMANTLE & REFIX REAR WINDSCREEN | \$120.00 (20 |
| | TO DISMANTLE & REFIX REAR EXHAUST | 11 \$100.00 X |
| | TO DISMANTLE & REFIX FUEL TANK | \$100.00 60 |
| | TO DISMANTLE & REFIX BOOTLID MECHANISM | 1 × 100.00 × |
| | TO RESET & REPROGRAMME SYSTEM | \$100.00 50 |
| | TO DISMANTLE & REFIX CUSHION UPHOLSTERY | \$120.00 |
| | TO DISMANTLE & REFIX REAR UNDER CARRIAGE | \$360.00 / 2-2 |
| | TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE | \$450.00 7 |
| | TO CONDUCT WHEEL ALIGNMENT | \$100.00 |
| | TO REFILL AIR CON GAS | \$100.00 |
| | TO SPRAY RUST PROOFING | \$200.00 120 |
| | LABOUR FOR PANEL BEATING & REPLACED PARTS | \$4,500.00 2200 |
| | TO PUTTY & SPRAY PAINTING | \$2,800.00 |
| | | TOTAL \$62.034.50 |

LKK Auto Consultants hence notify the Repairer of the following:

- To display damaged part(s, 'rring resurvey
 Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

TOTAL

\$62,034.50

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2060 (1370 - 201416