

Vehicle Damage Assessment Report for [SLC719C]

Estimate Created: 13/11/2022 23:33 by Insurlogic 1 (Insurlogic_Pte_Ltd)

Owned: 13/11/2022 23:54 by Insurlogic 1 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	Ergo Insurance	Claim Number
Claim Type	OD	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Nissan	Model	Note
Engine Type			
License Plate Number	SLC719C	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- Final review base on information provide by LKK: Concluded the cost of repair at \$17,391.50 with 9 days for repair

Insurlogic 1 (13/11/2022 23:54)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
STEERING AIRBAG		1	1500.00	10.00 %	1,650.00
STEERING AIRBAG WIRE		1	180.00	10.00 %	198.00
DASHBOARD AIRBAG		1	2200.00	10.00 %	2,420.00
AIR BAG ECU		1	1400.00	10.00 %	1,540.00
AIR BAG SENSOR LH		1	600.00	10.00 %	660.00
SEAT BELT RH		1	600.00	10.00 %	660.00
FRONT BONNET		1	450.00	10.00 %	495.00
FRONT BONNET LOCK		1	80.00	10.00 %	88.00
FRONT BONNET HINGE RH		1	45.00	10.00 %	49.50
FRONT BONNET HINGE LH		1	45.00	10.00 %	49.50
FRONT BONNET STOPPER RH		1	15.00	10.00 %	16.50
FRONT BONNET STOPPER LH		1	15.00	10.00 %	16.50
FRONT SUPPORT PANEL		1	250.00	10.00 %	275.00
FRONT SUPPORT GARNISH		1	180.00	10.00 %	198.00
FRONT FENDER RH		1	320.00	10.00 %	352.00
FRONT FENDER LH		1	320.00	10.00 %	352.00
FRONT FENDER SHIELD CLIP		1	40.00	10.00 %	44.00
FRONT GRILLE		1	210.00	10.00 %	231.00
FRONT EMBELM		1	55.00	10.00 %	60.50
HEADLAMP RH		1	450.00	10.00 %	495.00
HEADLAMP LH		1	450.00	10.00 %	495.00
FRONT BUMPER		1	350.00	10.00 %	385.00
FRONT BUMPER SIDE RETAINER RH		1	30.00	10.00 %	33.00
FRONT BUMPER SIDE RETAINER LH		1	30.00	10.00 %	33.00
FRONT BUMPER FOAM		1	150.00	10.00 %	165.00
FRONT BUMPER REINFORCEMENT		1	250.00	10.00 %	275.00
FRONT BUMPER REINFORCEMENT BRACKET RH		1	185.00	10.00 %	203.50
FRONT BUMPER REINFORCEMENT BRACKET LH		1	185.00	10.00 %	203.50
FRONT BUMPER TOW COVER		1	35.00	10.00 %	38.50

FRONT BUMPER CLIPS	1	25.00	10.00 %	27.50
AIRCON CONDENSER RADIATOR	1	125.00	10.00 %	137.50
RADIATOR FAN ASSY	1	320.00	10.00 %	352.00
SPARE TANK	1	70.00	10.00 %	77.00
WASHER TANK	1	125.00	10.00 %	137.50
INTAKE MANIFOLD	1	600.00	10.00 %	660.00
AIR CLEANER BOX	1	330.00	10.00 %	363.00
AIR CLEANER HOSE	1	140.00	10.00 %	154.00
ENGINE MOUNTING RH	1	180.00	10.00 %	198.00
FRONT FENDER SIDE BRACKET RH	1	40.00	10.00 %	44.00
FRONT CHASSIS BRACKET SIDE RH	1	50.00	10.00 %	55.00
RADIATOR TOP SEAL	1	50.00	10.00 %	55.00
CONDENSER SIDE GARNISH	1	55.00	10.00 %	60.50
FRONT FENDER TOP COVER RH	1	40.00	10.00 %	44.00
FAN BELT	1	50.00	10.00 %	55.00
AIR CLEANER BOX LOWER	1	320.00	10.00 %	352.00
RADIATOR SIDE SEAL	1	45.00	10.00 %	49.50

Parts Subtotal 14,921.50

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
AIRCON SUCTION HOSE		1.0	100.00	0.00 %	100.00
AIRCON DISCHARGE HOSE		1.0	100.00	0.00 %	100.00
FRONT NUMBER PLATE		1.0	40.00	0.00 %	40.00

Materials Subtotal 240.00

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
CHECK WIRING	RnR	30.00	0.00 %	30.00
RNR AIRCON CONDENSER AND REFILL AIRCON GAS	RnR	100.00	0.00 %	100.00
RNR FRONT DASHBOARD	RnR	200.00	0.00 %	200.00

REPLACE/REPAIR ACCIDENT AFFECTED ITEMS AND AREAS	RnR	800.00	0.00 %	800.00
---	-----	--------	--------	--------

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
PAINT ON ACCIDENT AFFECTED AREAS	Full spray	1100.00	0.00 %	1,100.00
General Labor Subtotal				1,130.00
Paint Labor Subtotal				1,100.00
Labor Subtotal				2,230.00

Summary

Repair Cost	17,391.50
Discount(0 %)	(0.00)
	17,391.50
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	17,391.50