

ASS. REC. BY: TaujiriREF: CS/EG122007585/Try3**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 600

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 446K **\$48k**

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLC719C Yr Regn: 2016 AprilType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Nissan Note c.c. 1198Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 154785 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SN171A19E12Z0971254Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 185/65R15R: 2

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 10/8/22Survey held at KFSDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

1) _____
Date/Time, File Return to?

2) _____

Rep. Format: _____

Lump Sum / I.B.A. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Photos _____

Others _____

TOTAL



蘭 福 星 嘜 工 廠 KAN FOOK SING MOTOR WORKSHOP

61 Defu Lane 12, Singapore 539147

Tel : (65) 6747 9560, 6858 2126, 6858 4361

Fax : (65) 6748 1006, 6281 8428

E-mail: kanfs@pacific.net.sg • Website: www.carparts.com.sg

Business Reg No. 221468-00E

GST Reg No. M9-0005333-E

INSURER: **ERGO Insurance Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMFG22005172	Date of Loss:	05/08/2022
Vehicle Reg. No.:	SLC719C	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	HWA SENG BUILDER PTE LTD		
Make/Model:	NISSAN NOTE, 1.2 (A)	Vehicle Reg. Date:	29/04/2016
Vehicle Colour:	METALLIC GREY		
Engine No:	HR12185104B	Chassis No:	JN1TAAE12Z0972254
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	15		
Description of Accident/Loss	REMARK : RPICE MIGHT BE DIFFREENT DUT TO STOCK AVAILABILITY		
Present Location:	KAN FOOK SING MOTOR WORKSHOP (DEFU)		

COST OF CLAIMS	Amount
Parts	16,703.50
Miscellaneous Items	120.00
Labour	1,370.00
Paintwork Labour	1,200.00
Towing	0.00
Calculated Gross Total (S\$)	19,393.50
- Excess (S\$)	600.00
(S\$)	18,793.50
+ GST 7.00% (S\$)	1,315.55
Nett Amount (S\$)	20,109.05

This claim is handled by: MT TAN

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 08 Aug 2022)
Parts: 144	NISSAN NOTE 1.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: Kan Fook Sing Motor Workshop/SLC719C/08/08/2022 15:32	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*STEERING AIR BAG	act✓ 0.00	0.00	*1,500.00 F
2	1		*STEERING AIR BAG WIRE	act✓ 0.00	0.00	*180.00 F
3	1		*DASHBOARD NO STOCK	de✓ 0.00	0.00	-
4	1		*DASHBOARD AIR BAG	act✓ 0.00	0.00	*2,200.00 F
5	1		*AIR BAG ECU NO STOCK	act✓ 0.00	0.00	-
6	1		*AIR BAG SENSOR RH	act✓ 0.00	0.00	*350.00 F
7	1		*AIR BAG SENSOR LH	act✓ 0.00	0.00	*350.00 F
8	1		*SEAT BELT RH	act✓ 0.00	0.00	*600.00 F
9	1		*SEAT BELT LH	? 0.00	0.00	*600.00 F
10	1		*FRONT WIPER CORNER GARNISH RH	? 0.00	0.00	*30.00 F
11	1		*FRONT WIPER CORNER GARNISH LH	? 0.00	0.00	*30.00 F
12	1		*FRONT BONNET	bt✓ 0.00	0.00	*450.00 F
13	1		*FRONT BONNET LOCK	bt✓ 0.00	0.00	*80.00 F
14	1		*FRONT BONNET HINGE RH	bt✓ 0.00	0.00	*45.00 F
15	1		*FRONT BONNET HINGE LH	bt✓ 0.00	0.00	*45.00 F
16	1		*FRONT BONNET STOPPER RH	mis✓ 0.00	0.00	*30.00 F
17	1		*FRONT BONNET STOPPER LH	mis✓ 0.00	0.00	*30.00 F
18	1		*FRONT SUPPORT PANEL	bt✓ 0.00	0.00	*250.00 F
19	1		*FRONT SUPPORT GARNISH	de✓ 0.00	0.00	*180.00 F
20	1		*FRONT LOWER MEMBER	? 0.00	0.00	*220.00 F
21	1		*FRONT FENDER RH	bt✓ 0.00	0.00	*320.00 F
22	1		*FRONT FENDER LH	bt✓ 0.00	0.00	*320.00 F
23	1		*FRONT FENDER SHIELD RH	de✓ 0.00	0.00	*95.00 F
24	20		*FRONT FENDER SHIELD CLIP	neu✓ 0.00	0.00	*50.00 F
25	1		*FRONT FENDER 1/4 GLASS MOULDING RH	? 0.00	0.00	*200.00 F
26	1		*FRONT FENDER 1/4 GLASS MOULDING LH	? 0.00	0.00	*200.00 F
27	1		*FRONT GRILLE	cur✓ 0.00	0.00	*210.00 F
28	1		*FRONT EMBLEM	cur✓ 0.00	0.00	*50.00 F
29	1		*FRONT HEADLAMP RH	cur✓ 0.00	0.00	*1,200.00 F
30	1		*FRONT HEADLAMP LH	cur✓ 0.00	0.00	*1,200.00 F
31	1		*FRONT BUMPER	de✓ 0.00	0.00	*350.00 F
32	1		*FRONT BUMPER SIDE RETAINER RH	dy✓ 0.00	0.00	*30.00 F
33	1		*FRONT BUMPER SIDE RETAINER LH	0.00	0.00	*30.00 F
34	1		*FRONT BUMPER FOAM NO STOCK	dis✓ 0.00	0.00	-
35	1		*FRONT BUMPER REINFORCEMENT	bt✓ 0.00	0.00	*250.00 F
36	1		*FRONT BUMPER REINFORCEMENT BRACKET RH	? 0.00	0.00	*220.00 F
37	1		*FRONT BUMPER REINFORCEMENT BRACKET LH	? 0.00	0.00	*220.00 F
38	1		*FRONT BUMPER TOW COVER NO STOCK	act✓ 0.00	0.00	-
39	10		*FRONT BUMPER CLIP	neu✓ 0.00	0.00	*25.00 F
40	1		*HORN	? 0.00	0.00	*80.00 F
41	1		*AIR CON CONDENSER	bt✓ 0.00	0.00	*480.00 F
42	1		*AIR CON LIQUID PIPE	? 0.00	0.00	*120.00 F

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
43	1		*AIR CON SUCTION HOSE	0.00	0.00	*250.00 F
44	1		*AIR CON DISCHARGE HOSE	0.00	0.00	*250.00 F
45	1		*RADIATOR	0.00	0.00	*380.00 F
46	1		*RADIATOR HOSE TOP	0.00	0.00	*40.00 F
47	1		*RADIATOR HOSE LOWER	0.00	0.00	*40.00 F
48	1		*RAIDATOR TOP MOUNTING RH	0.00	0.00	*25.00 F
49	1		*RAIDATOR TOP MOUNTING LH	0.00	0.00	*25.00 F
50	1		*RADIATOR FAN ASSY	0.00	0.00	*320.00 F
51	1		*SPARE TANK	0.00	0.00	*70.00 F
52	1		*WASHER TANK	0.00	0.00	*125.00 F
53	1		*INTAKE MANIFOLD NO STOCK	0.00	0.00	-
54	1		*AIR CLEANER BOX NO STOCK	0.00	0.00	-
55	1		*AIR CLEANER HOSE	0.00	0.00	*150.00 F
56	1		*ALTERNATOR NO STOCK	0.00	0.00	-
57	1		*ENGINE MOUNTING RH	0.00	0.00	*195.00 F
58	1		*ENGINE MOUNTING LH	0.00	0.00	*85.00 F
59	1		*ENGINE MOUNTING RR	0.00	0.00	*80.00 F
60	1		*FRONT SIDE MIRROR RH	0.00	0.00	*330.00 F

F=Franchise part.

Sub Total (S\$)	15,185.00
+ Margin on L,N Items 10.00% (S\$)	1,518.50
Total Parts (S\$)	16,703.50

Kan Fook Sing Motor Workshop/SLC719C/08/08/2022 15:32. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRONT FENDER 1/4 GLASS GUM LH	40.00
2	1	FRONT FENDER 1/4 GLASS GUM RH	40.00
3	1	FRONT NUMBER PLATE	40.00
Sub Total (S\$)			120.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	SPRAYPAINTING CHARGES	New	1,200.00
<u>Labour Items</u>			
2	TO CHECK WIRING SYSTEM	New	50.00
3	TO REMOVE/REFIT/REFILL AIR CON GAS	New	100.00
4	TO REMOVE/REFIT DASHBOARD	New	240.00
5	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	980.00
Gross Labour Cost (S\$)			2,570.00

Kan Fook Sing Motor Workshop/SLC719C/08/08/2022 15:32. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Taufik 97495749 / 62563561
 not Authorise, Revert
 Ex: 1600
 10/8/22 @ 1pm
 Resurvey before paint
 Taufik @ lkhankun
 09 days.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: