



簡福星噴漆工廠
KAN FOOK SING MOTOR WORKSHOP

61 Defu Lane 12, Singapore 539147

Tel : (65) 6747 9560, 6858 2126, 6858 4361

Fax : (65) 6748 1006, 6281 8428

E-mail: kanfs@pacific.net.sg • Website: www.carparts.com.sg

Business Reg No. 221468-006

GST Reg No. M9-0005333-E

INSURER: **ERGO Insurance Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMFG22005172	Date of Loss:	05/08/2022
Vehicle Reg. No.:	SLC719C	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	HWA SENG BUILDER PTE LTD		
Make/Model:	NISSAN NOTE, 1.2 (A)	Vehicle Reg. Date:	29/04/2016
Vehicle Colour:	METALLIC GREY		
Engine No:	HR12185104B	Chassis No:	JN1TAAE12Z0972254
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	15		
Description of Accident/Loss	REMARK : RPICE MIGHT BE DIFFREENT DUT TO STOCK AVAILABILITY		
Present Location:	KAN FOOK SING MOTOR WORKSHOP (DEFU)		

COST OF CLAIMS	Amount
Parts	16,703.50
Miscellaneous Items	120.00
Labour	1,370.00
Paintwork Labour	1,200.00
Towing	0.00
Calculated Gross Total (S\$)	19,393.50
- Excess (S\$)	600.00
(S\$)	18,793.50
+ GST 7.00% (S\$)	1,315.55
Nett Amount (S\$)	20,109.05

This claim is handled by: MT TAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Aug 2022)

Parts: 144 NISSAN NOTE 1.2 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Kan Fook Sing Motor Workshop/SLC719C/08/08/2022 15:32

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*STEERING AIR BAG	act ✓ 0.00	0.00	*1,500.00 F
2	1		*STEERING AIR BAG WIRE	act ✓ 0.00	0.00	*180.00 F
3	1		*DASHBOARD	de ✓ 0.00	0.00	-
			NO STOCK			
4	1		*DASHBOARD AIR BAG	act ✓ 0.00	0.00	*2,200.00 F
5	1		*AIR BAG ECU	act ✓ 0.00	0.00	-
			NO STOCK			
6	1		*AIR BAG SENSOR RH	act ✓ 0.00	0.00	*350.00 F
7	1		*AIR BAG SENSOR LH	act ✓ 0.00	0.00	*350.00 F
8	1		*SEAT BELT RH	act ✓ 0.00	0.00	*600.00 F
9	1		*SEAT BELT LH	? 0.00	0.00	*600.00 F
10	1		*FRONT WIPER CORNER GARNISH RH	? 0.00	0.00	*30.00 F
11	1		*FRONT WIPER CORNER GARNISH LH	? 0.00	0.00	*30.00 F
12	1		*FRONT BONNET	bt ✓ 0.00	0.00	*450.00 F
13	1		*FRONT BONNET LOCK	bt ✓ 0.00	0.00	*80.00 F
14	1		*FRONT BONNET HINGE RH	bt ✓ 0.00	0.00	*45.00 F
15	1		*FRONT BONNET HINGE LH	bt ✓ 0.00	0.00	*45.00 F
16	1		*FRONT BONNET STOPPER RH	mis ✓ 0.00	0.00	*30.00 F
17	1		*FRONT BONNET STOPPER LH	mis ✓ 0.00	0.00	*30.00 F
18	1		*FRONT SUPPORT PANEL	bt ✓ 0.00	0.00	*250.00 F
19	1		*FRONT SUPPORT GARNISH	de ✓ 0.00	0.00	*180.00 F
20	1		*FRONT LOWER MEMBER	? 0.00	0.00	*220.00 F
21	1		*FRONT FENDER RH	bt ✓ 0.00	0.00	*320.00 F
22	1		*FRONT FENDER LH	bt ✓ 0.00	0.00	*320.00 F
23	1		*FRONT FENDER SHIELD RH	de ✓ 0.00	0.00	*95.00 F
24	20		*FRONT FENDER SHIELD CLIP	mis ✓ 0.00	0.00	*50.00 F
25	1		*FRONT FENDER 1/4 GLASS MOULDING RH	? 0.00	0.00	*200.00 F
26	1		*FRONT FENDER 1/4 GLASS MOULDING LH	? 0.00	0.00	*200.00 F
27	1		*FRONT GRILLE	act ✓ 0.00	0.00	*210.00 F
28	1		*FRONT EMBLEM	act ✓ 0.00	0.00	*50.00 F
29	1		*FRONT HEADLAMP RH	act ✓ 0.00	0.00	*1,200.00 F
30	1		*FRONT HEADLAMP LH	act ✓ 0.00	0.00	*1,200.00 F
31	1		*FRONT BUMPER	de ✓ 0.00	0.00	*350.00 F
32	1		*FRONT BUMPER SIDE RETAINER RH	de ✓ 0.00	0.00	*30.00 F
33	1		*FRONT BUMPER SIDE RETAINER LH	0.00	0.00	*30.00 F
34	1		*FRONT BUMPER FOAM	act ✓ 0.00	0.00	-
			NO STOCK			
35	1		*FRONT BUMPER REINFORCEMENT	bt ✓ 0.00	0.00	*250.00 F
36	1		*FRONT BUMPER REINFORCEMENT BRACKET RH	? 0.00	0.00	*220.00 F
37	1		*FRONT BUMPER REINFORCEMENT BRACKET LH	? 0.00	0.00	*220.00 F
38	1		*FRONT BUMPER TOW COVER	act ✓ 0.00	0.00	-
			NO STOCK			
39	10		*FRONT BUMPER CLIP	act ✓ 0.00	0.00	*25.00 F
40	1		*HORN	? 0.00	0.00	*80.00 F
41	1		*AIR CON CONDENSER	bt ✓ 0.00	0.00	*480.00 F
42	1		*AIR CON LIQUID PIPE	? 0.00	0.00	*120.00 F

Kan Fook Sing Motor Workshop/SLC719C/08/08/2022 15:32. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
43	1		*AIR CON SUCTION HOSE	0.00	0.00	*250.00 F
44	1		*AIR CON DISCHARGE HOSE	0.00	0.00	*250.00 F
45	1		*RADIATOR	0.00	0.00	*380.00 F
46	1		*RADIATOR HOSE TOP	0.00	0.00	*40.00 F
47	1		*RADIATOR HOSE LOWER	0.00	0.00	*40.00 F
48	1		*RAIDATOR TOP MOUNTING RH	0.00	0.00	*25.00 F
49	1		*RAIDATOR TOP MOUNTING LH	0.00	0.00	*25.00 F
50	1		*RADIATOR FAN ASSY	0.00	0.00	*320.00 F
51	1		*SPARE TANK	0.00	0.00	*70.00 F
52	1		*WASHER TANK	0.00	0.00	*125.00 F
53	1		*INTAKE MANIFOLD NO STOCK	0.00	0.00	-
54	1		*AIR CLEANER BOX NO STOCK	0.00	0.00	-
55	1		*AIR CLEANER HOSE	0.00	0.00	*150.00 F
56	1		*ALTERNATOR NO STOCK	0.00	0.00	-
57	1		*ENGINE MOUNTING RH	0.00	0.00	*195.00 F
58	1		*ENGINE MOUNTING LH	0.00	0.00	*85.00 F
59	1		*ENGINE MOUNTING RR	0.00	0.00	*80.00 F
60	1		*FRONT SIDE MIRROR RH	0.00	0.00	*330.00 F

F=Franchise part.

Sub Total (S\$)	15,185.00
+ Margin on L,N Items 10.00% (S\$)	1,518.50
Total Parts (S\$)	16,703.50

Kan Fook Sing Motor Workshop/SLC719C/08/08/2022 15:32. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRONT FENDER 1/4 GLASS GUM LH	? 40.00
2	1	FRONT FENDER 1/4 GLASS GUM RH	? 40.00
3	1	FRONT NUMBER PLATE	mis 40.00
Sub Total (S\$)			120.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	SPRAYPAINTING CHARGES	New 1100	1,200.00
<u>Labour Items</u>			
2	TO CHECK WIRING SYSTEM	New 30	50.00
3	TO REMOVE/REFIT/REFILL AIR CON GAS	New ✓	100.00
4	TO REMOVE/REFIT DASHBOARD	New 200	240.00
5	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New 800	980.00
Gross Labour Cost (S\$)			2,570.00

Kan Fook Sing Motor Workshop/SLC719C/08/08/2022 15:32. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Taufik 97495749 / 62563561

Not Authorise, Revert

Ex: 600

10/8/22 @ 1pm

Resurvey before paint

Taufik @ Lkhantun

09 days.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: