

# COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969

Our Ref : 205525888 Via Fax : email  
Date : 10-08-12 Your Insured : YP 9162B  
Time of Fax : \_\_\_\_\_ Date of Acc : 09-08-12

Attn: Motor Claims Department

Lompac

Dear Sirs

**SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH**

21151E

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

|                             |  |
|-----------------------------|--|
| ◆ Lim Kwok Eng              | Tel: 6214 8355 or HP: 9824 0811        |
| ◆ <b>Jumani Bin Masudin</b> | <b>Tel: 6214 8315 or HP: 9635 5305</b> |
| ◆ Lim Tien Siong            | Tel: 6214 8398 or HP: 9635 8546        |
| ◆ Chiang Liat Choon         | Tel: 6214 8314 or HP: 9296 6006        |

} **jumanibm@cde.com.sg**  
**Fax no. 6546 8156**

→ If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

For Vice President  
Taxi Accident Repair

Job: ARC Repair TP(CLSO)1

**JOB CARD** Sales Order:


JC No: 305525888

|  |  |   |
|--|--|---|
| FOMER<br>AS COMFORT TRANSPORTATION PTE LTD<br>FOMER NO. 7010045<br>ADDRESS 383 SIN MING DRIVE<br>Singapore SINGAPORE 575717<br>(R) 65508755 (O)<br>(P) | REGN NO:<br><b>SHC1151E</b>              | MILEAGE                                 |
|  | MAKE:<br><b>TOYOTA</b>                   | FUEL<br>E.....1/2.....F                 |
|  | MODEL:<br><b>PRIUS HYBRID(G4)</b>        | DATE/TIME IN<br><b>10.08.2022 09:50</b> |
|  | YR OF MANU.<br><b>07.10.2016</b>         | TARGET DATE                             |
|  | CHASSIS CODE<br><b>JTDKB3FU903531260</b> | COMPLETION DATE/TIME:                   |

Accident Date: 09.08.2022  
 Insured: 3P 09.08.2022

JOB DESCRIPTION

NO LABOR CODE DESCRIPTION



Checked & Passed Out By: \_\_\_\_\_

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Checklist/Check Slip

Exit Pass

Job No.: SHC1151E

JU LONPAC

Vehicle No.:

SHC1151E

Signature/Date

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

**COMFORTDELGRO ENGINEERING PTE LTD**

**REPAIR ESTIMATE\***

VEHICLE NO **SHC1151E**  
 MAKE **TOYOTA**  
 MODEL **PRIUS**

DATE: **10.08.22**  
 MVA **JUMANI**  
 DOA: **09.08.22**

**LONPAC**

| Qty | Parts Description/ Labour   | Type | Unit Price | Amount            |
|-----|-----------------------------|------|------------|-------------------|
| 1   | REAR BUMPER ASSY            |      |            | \$503.04          |
| 1   | REAR BUMPER CENTRE MLDG     |      |            | \$654.96          |
| 1   | REAR BUMPER BEAM            |      |            | \$378.33          |
| 10  | REAR BUMPER CLIPS           |      |            | \$22.00           |
|     | REAR BUMPER TOW COVER       |      |            | \$82.70           |
| 1   |                             |      |            |                   |
|     | <b>SUB TOTAL</b>            |      |            | <b>\$2,637.63</b> |
|     | <b>LESS 25%</b>             |      |            | \$410.25          |
|     | <b>DISCOUNTED TOTAL</b>     |      |            | <b>\$1,230.78</b> |
|     |                             |      |            |                   |
|     | REVERSE SENSOR              |      |            | \$135.70          |
|     | REAR BUMPER MAT             |      |            | \$50.00           |
|     |                             |      |            | <b>\$185.70</b>   |
|     | <b>Labour Charge</b>        |      |            |                   |
|     | PANEL BEATING –             |      |            | \$400.00          |
|     | SPRAY PAINT                 |      |            | \$300.00          |
|     | REMOVE/REFIX REVERSE SENSOR |      |            | \$50.00           |
|     | ADVERTISEMENT LOGO - BUMPER |      |            | \$50.00           |
|     | ADVERTISEMENT LOGO - FENDER |      |            | \$200.00          |
|     |                             |      |            |                   |
|     | <b>TOTAL LABOUR</b>         |      |            | <b>\$1,000.00</b> |
|     |                             |      |            |                   |
|     | <b>ESTIMATE TOTAL</b>       |      |            | <b>\$3,023.93</b> |

NET  
NET

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

INSURER ENQUIRY

# Find insurer

Vehicle reg. no.

YP9162B

Date of Accident

09/08/2022 

Reset

## % RESULT & RECEIPT

### TP Insurer Enquiry

Insurance ..... **Lonpac Insurance Bhd**

Period of Insurance ..... **15/08/2021 - 14/08/2022**

Requested By ..... **Por Moy Juan (COMFORTDELG...**

Requested Date ..... **10/08/2022 10:59**

#### Payment details

Request Amount: **S\$1.87**

GST Amount: **S\$0.13**

Total Amount Due (GST Inclusive): **S\$2**

#### General Insurance Association

Records Management Centre

GST Registration No: **M400017735**

*9/11/22*