

Date: 13/08/2022
 Vehicle No: SMZ3573C
 Model: MERCEDES BENZ GLC300 M-HYBRID COUPE
 Chassis: WDC2533842F730682-2019
 Reg.Year: 2020

*NOT Not hail
 Recovery B&paint*

Third Party Insurer: AIG
 Third Party Veh No: GBL9036B
 Date of Accident: 06/08/2022
 Estimator: TING AN
 Surveyor:

ESTIMATE

Super Glue (C)

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT WINDSCREEN GLASS	1		\$1,875.00
2	FRONT WINDSCREEN RAIN SENSOR	1		\$475.00
3	FRONT WIPER ARM LH <i>blade</i>	1		<i>C</i> \$180.00
4	FRONT WIPER ARM RH <i>blade</i>	1		<i>C</i> \$180.00
5	FRONT BONNET	1		<i>R</i> \$3,540.00
6	FRONT BONNET EMBLEM	1		<i>M</i> \$80.00
7	FRONT HEADLAMP LH	1		<i>C</i> \$6,390.00
8	FRONT GRILLE BASE	1		<i>C</i> \$190.00
9	FRONT GRILLE LOGO EMBLEM	1		<i>M</i> \$250.00
10	FRONT GRILLE OUTER GARNISH	1		<i>C</i> \$270.00
11	FRONT GRILLE CHROME MOULDING LH	1		<i>C</i> \$240.00
12	FRONT GRILLE TOP CHROME MOULDING LH	1		<i>C</i> \$440.00
13	FRONT GRILLE BOTTOM CHROME MOULDING LH	1		<i>C</i> \$440.00
14	FRONT BUMPER	1		<i>R</i> \$3,400.00
15	FRONT BUMPER LOWER GRILLE	1		<i>C</i> \$90.00
16	FRONT BUMPER LOWER GRILLE LH	1		<i>C</i> \$150.00
17	FRONT BUMPER PARKING SENSOR	2	\$150.00	\$300.00
18	FRONT BUMPER LOWER CHROME MOULDING LH	1		<i>C</i> \$150.00
19	FRONT BUMPER LOWER CHROME MOULDING CENTER	1		<i>C</i> \$600.00
20	FRONT BUMPER SIDE GARNISH COVER LH	1		<i>C</i> \$140.00
21	FRONT FENDER LH	1		<i>R</i> \$1,300.00
22	FRONT FENDER WHEEL ARCH COVER LH	1		<i>C</i> \$260.00
23	FRONT DOOR OUTER HANDLE LH	1		<i>C</i> \$640.00
24	FRONT DOOR OUTER MOULDING LH	1		<i>R</i> \$200.00
25	A-PILLAR MOULDING LH	1		<i>C</i> \$300.00
26	A-PILLAR CHROME MOULDING LH	1		<i>C</i> \$260.00
27	FRONT SIDE MIRROR ASSY LH	1		<i>C</i> \$2,250.00
28	REAR DOOR DOOR OUTER HANDLE LH	1		<i>C</i> \$640.00
29	REAR DOOR OUTER MOULDING LH	1		<i>R</i> \$200.00
30	REAR FENDER WHEEL ARCH COVER LH	1		<i>C</i> \$320.00
31	A-PILLAR LH	1		REPAIR
32	FRONT DOOR LH	1		REPAIR
33	REAR DOOR LH	1		REPAIR
34	REAR FENDER LH	1		REPAIR
SUB TOTAL				\$25,750.00
LESS 10%				-\$2,575.00
PARTS TOTAL				\$23,175.00

Handwritten checkmarks and symbols (X, C, R, M) next to each row in the table.

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 13/08/2022
 Vehicle No: SMZ3573C
 Model: MERCEDES BENZ GLC300 M-HYBRID COUPE
 Chassis: WDC2533842F730682-2019
 Reg.Year: 2020

Third Party Insurer: AIG
 Third Party Veh No: GBL9036B
 Date of Accident: 06/08/2022
 Estimator: TING AN
 Surveyor:

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT WINDSCREEN SEALANT	1		\$100.00
2	FRONT IU STICKER	1		\$20.00
3	FRONT BUMPER CLIPS	1		<i>na</i> \$50.00
4	FRONT FENDER WHEEL ARCH LH CLIPS	1		<i>na</i> \$40.00
5	SIDE STEP LH	1		<i>Per</i> \$1,400.00
6	REAR FENDER WHEEL ARCH CLIPS LH	1		<i>na</i> \$40.00
			S/N TOTAL	\$1,650.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST AFFECTED AREAS & ETC. \$1,500.00 *400*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT BUMPER, FRONT FENDER LH, FRONT DOOR LH, REAR DOOR LH, REAR FENDER LH & ETC. \$1,500.00 *1400*

LABOUR CHARGES TO REMOVE & REPLACE FRONT WINDSCREEN GLASS, FRONT WINDSCREEN MOULDING, FRONT WINDSCREEN SEALANT & ETC. \$150.00 *?*

TO DIAGNOSIS FAULT CODE & RESET MEMORY. \$150.00 *?*

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC. \$120.00 *300*

LABOUR TOTAL \$3,420.00

TING AN

TOTAL \$28,245.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

