

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

10/08/2022 11:36

JOB-NO: 50114376

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 2

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHB3139J

TRANS: AUTO

CHASSIS: KMHLB41UMGU092312

MAKE / MODEL: HYUNDAI / i40

ENGINE: D4FDGU660932

OWNER'S INSURER: AXA INSURANCE SINGAPORE PTE LTD

JOB-CODE: TP

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 TO STRAIGHTEN AND PANEL BEAT OF ACCIDENT AFFECTED AREA	1.00	1,600.00	0.00	1,600.00	1991	Y	_____
2 TO RUST PROOFING OF THE AFFECTED AREA	1.00	170.00	0.00	170.00	30	Y	_____
3 TO REMOVE AND REFIT OF NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR	1.00	200.00	0.00	200.00	50	Y	_____
4 TO REFIT REAR REVERSE SENSOR	1.00	100.00	0.00	100.00	30 X	Y	_____
5 TO DIAGNOSTIC, CHECK WIRING AND LIGHTING SYSTEM AND CLEAR FAULT CODE	1.00	200.00	0.00	200.00	30	Y	_____
6 TO REMOVE AND REFIT REAR WINDSCREEN GLASS AND QUARTER GLASS TO ENABLE BODYWORK REPAIR	1.00	260.00	0.00	260.00	12 150	Y	_____
7 TO TRANSFER OF BOTH FRONT AND REAR DOOR MECHANISM TO NEW DOOR AND PERFORM WATER SEEPAGE TEST	1.00	170.00	0.00	170.00	80	Y	_____
8 TO RESPRAY FRONT DOOR PANEL	1.00	250.00	0.00	250.00	200	Y	_____
9 TO RESPRAY SIDE SKIRT RH Port side mirror	1.00	250.00	0.00	250.00	30	Y	_____
10 TO RESPRAY REAR RH DOOR PANEL	1.00	250.00	0.00	250.00	200	Y	_____
11 TO RESPRAY REAR RH QUARTER PANEL	1.00	250.00	0.00	250.00	200	Y	_____
12 TO RESPRAY FRONT AND REAR OUTER DOOR HANDLE AND COVER	1.00	250.00	0.00	250.00	30	Y	_____
13 TO RESPRAY FRONT FENDER PANEL	1.00	250.00	0.00	250.00	X	Y	_____
TOTAL:		4,200.00	0.00	4,200.00			_____
MATERIALS							
1 FRONT RH DOOR PANEL / 00	1.00	2,256.00	451.20	1,804.80	L	Y	_____
2 FRONT RH SIDE MIRROR / BR	1.00	586.30	117.26	469.04	L	Y	_____
3 FRONT RH OUTER DOOR GLASS MOULDING	1.00	107.85	21.57 / BT	86.28	L	Y	_____
4 FRONT RH DOOR GLASS / CUT	1.00	705.68	141.14	564.54	L	Y	_____
5 FRONT RH DOOR POWER WINDOW X REGULATOR	1.00	350.10	70.02	280.08	L	Y	_____
6 FRONT RH OUTER DOOR HANDLE X R	1.00	68.90	13.78	55.12	L	Y	_____
7 FRONT RH OUTER DOOR HANDLE COVER X R	1.00	10.75	2.15	8.60	L	Y	_____
8 REAR RH DOOR PANEL / 00	1.00	2,201.00	440.20	1,760.80	L	Y	_____
9 REAR RH OUTER DOOR HANDLE X	1.00	68.90	13.78	55.12	L	Y	_____
10 REAR RH OUTER DOOR HANDLE COVER X	1.00	10.85	2.17	8.68	L	Y	_____
11 REAR RH QUARTER PANEL / 00	1.00	2,171.50	434.30	1,737.20	L	Y	_____
12 REAR RH DOOR GLASS X	1.00	705.68	141.14	564.54	L	Y	_____

G-STAR-WI-ET-001-02-Rev00

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
13 FRONT RH DOOR FRAME UPPER CHROME X MOULDING	1.00	39.80	7.96	31.84	L	Y	
14 FRONT RH DOOR FRAME REAR BLACK CVT MOULDING	1.00	71.50	14.30	57.20	L	Y	
15 FRONT RH DELTA GARNISH X	1.00	102.30	20.46	81.84	L	Y	
16 FRONT DOOR "COMFORT DELGRO" / nrc STICKER	1.00	120.00	0.00	120.00	S	Y	
17 FRONT AND REAR DOOR MOULDING CLIP X SET	1.00	55.00	0.00	55.00	S	Y	
18 REAR DOOR "GOOGLE PLAY STORE" / nrc STICKER	1.00	100.00	0.00	100.00	S	Y	
19 REAR DOOR "COMFORT DELGRO" STICKER / nrc	1.00	100.00	0.00	100.00	S	Y	
20 REAR WINDSCREEN PRIMER / nrc	2.00	100.00	0.00	100.00	S	Y	
21 REAR WINDSCREEN SEALANT / nrc	3.00	150.00	0.00	150.00	S	Y	
22 REAR QUARTER PANEL SEALANT / nrc	2.00	120.00	0.00	120.00	S	Y	
TOTAL:		10,202.11	1,891.43	8,310.68			
Supp- Rear Windscreen moulding \$101.42 / nrc (L)		14,402.11	1,891.43	12,510.68			
TOTAL PARTS & LABOUR :							

EXCESS/LOADING:\$ 0.00

No. Of Day: 7 daysRE-SURVEY: BEFORE/AFTER PAINTING
PART-BY-PART OR LUMP SUM: S\$DATE OF SURVEY: 11, 8, 22, 10.10.20 m.L
SURVEYED BY: Steve CLKK

CONTACT NO: _____ FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX: