

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

10/08/2022 11:36

JOB-NO: 50114376

OWNER'S PARTICULARSNAME: CityCab PTE LTD (Fleet)
ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0CONTACT: 65533880
64739522

Page 1 of 2

VEHICLE DETAILSLICENSE NO: SHB3139J
MAKE / MODEL: HYUNDAI / i40
OWNER'S INSURER: AXA INSURANCE SINGAPORE PTE LTD
JOB-CODE: TP

TRANS: AUTO

CHASSIS: KMHLB41UMGU092312
ENGINE: D4FDGU660932

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 TO STRAIGHTEN AND PANEL BEAT OF ACCIDENT AFFECTED AREA	1.00	1,600.00	0.00	1,600.00	1991	Y	_____
2 TO RUST PROOFING OF THE AFFECTED AREA	1.00	170.00	0.00	170.00	31	Y	_____
3 TO REMOVE AND REFIT OF NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR	1.00	200.00	0.00	200.00	50	Y	_____
4 TO REFIT REAR REVERSE SENSOR	1.00	100.00	0.00	100.00	30 X	Y	_____
5 TO DIAGNOSTIC, CHECK WIRING AND LIGHTING SYSTEM AND CLEAR FAULT CODE	1.00	200.00	0.00	200.00	30	Y	_____
6 TO REMOVE AND REFIT REAR WINDSCREEN GLASS AND QUARTER GLASS TO ENABLE BODYWORK REPAIR	1.00	260.00	0.00	260.00	12. 150 180	Y	_____
7 TO TRANSFER OF BOTH FRONT AND REAR DOOR MECHANISM TO NEW DOOR AND PERFORM WATER SEEPAGE TEST	1.00	170.00	0.00	170.00	80 100	Y	_____
8 TO RESPRAY FRONT DOOR PANEL	1.00	250.00	0.00	250.00	200	Y	_____
9 TO RESPRAY SIDE SKIRT RH front side mirror	1.00	250.00	0.00	250.00	30 50	Y	_____
10 TO RESPRAY REAR RH DOOR PANEL	1.00	250.00	0.00	250.00	200	Y	_____
11 TO RESPRAY REAR RH QUARTER PANEL	1.00	250.00	0.00	250.00	200	Y	_____
12 TO RESPRAY FRONT AND REAR OUTER DOOR HANDLE AND COVER	1.00	250.00	0.00	250.00	30	Y	_____
13 TO RESPRAY FRONT FENDER PANEL	1.00	250.00	0.00	250.00	X	Y	_____
TOTAL:		4,200.00	0.00	4,200.00	2070	✓	_____
<u>MATERIALS</u>							
1 FRONT RH DOOR PANEL / DD	1.00	2,256.00	451.20	1,804.80	✓	L	Y
2 FRONT RH SIDE MIRROR / BR	1.00	586.30	117.26	469.04	✓	L	Y
3 FRONT RH OUTER DOOR GLASS MOULDING	1.00	107.85	21.57	86.28	✓	L	Y
4 FRONT RH DOOR GLASS / CUT	1.00	705.68	228.20	564.54	141.14	1482.56	✓ Y
5 FRONT RH DOOR POWER WINDOW REGULATOR X NN	1.00	350.10	70.02	280.08		L	Y
6 FRONT RH OUTER DOOR HANDLE X R	1.00	68.90	13.78	55.12		L	Y
7 FRONT RH OUTER DOOR HANDLE COVER X R	1.00	10.75	2.15	8.60		L	Y
8 REAR RH DOOR PANEL / DD	1.00	2,201.00	440.20	1,760.80	✓	L	Y
9 REAR RH OUTER DOOR HANDLE X NN	1.00	68.90	13.78	55.12		L	Y
10 REAR RH OUTER DOOR HANDLE COVER X NN	1.00	10.85	2.17	8.68		L	Y
11 REAR RH QUARTER PANEL / DD	1.00	2,171.50	434.30	1,737.20	✓	L	Y
12 REAR RH DOOR GLASS X NN	1.00	705.68	141.14	564.54		L	Y

G-STAR-WI-ET-001-02-Rev00

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
13 FRONT RH DOOR FRAME UPPER CHROME MOULDING	1.00	NN 39.80	7.96	31.84	L	Y	
14 FRONT RH DOOR FRAME REAR BLACK MOULDING	1.00		14.30	57.20	L	Y	
15 FRONT RH DELTA GARNISH	1.00	NN 102.30	20.46	81.84	L	Y	
16 FRONT DOOR "COMFORT DELGRO" STICKER	1.00	120.00	0.00	80 120.00	S	Y	
17 FRONT AND REAR DOOR MOULDING CLIP SET	1.00	NN 55.00	0.00	55.00	S	Y	6179.28
18 REAR DOOR "GOOGLE PLAY STORE" STICKER	1.00	100.00	0.00	40 100.00	S	Y	
19 REAR DOOR "COMFORT DELGRO" STICKER	1.00	100.00	0.00	80 100.00	S	Y	
20 REAR WINDSCREEN PRIMER	2.00	100.00	0.00	40 100.00	S	Y	
21 REAR WINDSCREEN SEALANT	3.00	150.00	0.00	40 150.00	S	Y	
22 REAR QUARTER PANEL SEALANT	2.00	120.00	0.00	20 120.00	S	Y	
TOTAL:		10,202.11	891.43	8,310.68			290
Supp- Rear Windscreen moulding \$101.42 / nec (L)		14,402.11	1,891.43	12,510.68			8539.28
TOTAL PARTS & LABOUR :							

EXCESS/LOADING:\$ 0.00

12,592.08

L/S - 6831.42
= 6850

No. Of Day:

7 days

RE-SURVEY: BEFORE/AFTER PAINTING
PART-BY-PART OR LUMP SUM: S\$

DATE OF SURVEY: 11, 8, 22, 10.10.24 m.L

SURVEYED BY:

Steve (CLKK)

CONTACT NO:

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR
STA AUTOCENTRE
TEL:

FAX: