

**Note: This document has not been finalised.**

# **LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance  
(Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 11 Aug 2022

## **Preliminary Advice**

|                    |                                                                                          |                         |                    |
|--------------------|------------------------------------------------------------------------------------------|-------------------------|--------------------|
| Vehicle No         | : SNB4597S                                                                               | Accident Date           | : 28/07/2022       |
| Make               | : TOYOTA                                                                                 | Policy No.              | :                  |
|                    | HARRIER                                                                                  |                         | DMPCSNW00173432100 |
| Assignment Date    | : 10/08/2022                                                                             | Excess                  | : S\$1,500.00      |
| Date of Inspection | : 11/08/2022                                                                             | Est. Duration of Repair | : 14               |
| Inspection At      | : CARTIMES AUTOLUTION PTE LTD<br>160 SIN MING DRIVE #02-04 AUTOCITY,<br>SINGAPORE 575722 |                         |                    |

## **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

|                             |                |
|-----------------------------|----------------|
| Repairer's Estimate (Gross) | :S\$ 15,087.00 |
| Revised Amount              | :S\$ 11,355.00 |
| Check Items (Estimated)     | :S\$ 6,537.00  |
| Total                       | :S\$ 17,892.00 |

Lump Sum Repair :S\$

## **Total Loss Consideration**

|                    |                 |
|--------------------|-----------------|
| New for Old Value  | :S\$            |
| Pre-Accident Value | :S\$ 188,000.00 |
| COE / PARF Rebate  | :S\$ 68,814.00  |

|                   |                 |
|-------------------|-----------------|
| Salvage Value     | :S\$            |
| Margin for Repair | :S\$ 119,186.00 |

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.