



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Ref: CS3/LPC22004142/Rce2-1

Date: 25/08/2022

Code: LPC2

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	GBE 8357T	<b>Veh. Inspected</b>	GBH 9293X
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	21/22/22/VC05/025752	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	HUEY NI	<b>Assign Date</b>	28/06/2022

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	TOYOTA DYNA 150 5MT	<b>c.c</b>	2982
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2018
<b>Chassis No.</b>	JTFAT35Y80K211664	<b>Colour</b>	WHITE
<b>Odometer</b>	64380 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
<b>General</b>	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	195/75 R15C	BRIDGESTONE	7 mm
<b>L/H Front Tyre</b>	195/75 R15C	BRIDGESTONE	7 mm
<b>R/H Rear Tyre</b>	155 R12C (D)	BRIDGESTONE	5/5 mm
<b>L/H Rear Tyre</b>	155 R12C (D)	BRIDGESTONE	5/5 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	04/05/2022	<b>Inspection Date</b>	05/05/2022
<b>Survey held at</b>	39 WOODLANDS CLOSE #01-35 MEGA@WOODLANDS		
<b>Repairer</b>	FA AUTOWORKS PTE LTD		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **10 Working Days**