



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2301341

INV Date 07/03/2023

Reference CC4/LPC22007608/Epa3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SNB 4732T

Insured Veh. XE 1181T

Claim No. 22/22/22/VC05/026120

Policy No. Z22VC05013063

Accident Date 05/08/2022

Inspection Date 18/10/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC22007608/Epa3q2 Date: 07/03/2023 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XE 1181T	Veh. Inspected	SNB 4732T	
Policy No.	Z22VC05013063	Coverage (\$)	0.00	
Claim No.	22/22/22/VC05/026120	Excess (\$)	0.00	
Assign From	ENG HUEY NI	Assign Date	10/08/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	JTDZS3EU20J067658	Colour	GREY	
Odometer	11364 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/55 R15	BRIDGESTONE	4 mm	
L/H Front Tyre	195/55 R15	BRIDGESTONE	4 mm	
R/H Rear Tyre	195/55 R15	BRIDGESTONE	4 mm	
L/H Rear Tyre	195/55 R15	BRIDGESTONE	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/08/2022	Inspection Date	18/10/2022	
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNB 4732T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SUNDRIES (SN)	NECESSARY	50.00	50.00
1	COVER ,RR BUMPER (SN)	DENTED	602.60	602.60
1	REINFORCEMENT (SN)	NOT NECESSARY	234.70	-
1	BACK SENSOR 1G3 GREY ME (SN)	NOT NECESSARY	101.05	-
1	PIECE ,RR BUMPER (SN)	NECESSARY	45.00	45.00
			1,033.35	697.60
	<u>LABOUR</u>			
	RESET AND REPROGRAMME ETC.		180.00	180.00
	DRILL HOLE TO INSTALL REVERSE SENSOR .		180.00	180.00
	CHR REAR WIRING SYSTEM AND CONDUCT WATER TEST.		180.00	180.00
	REPLACE AND REALIGN REAR BUMPR .		900.00	720.00
	SPRAY PAINT ON REAR BUMPR .		737.50	590.00
	LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION ON REAR BUMPER .		91.59	91.59
			2,269.09	1,941.59
GRAND TOTAL			3,302.44	2,639.19

RECOMMENDED COST OF REPAIRS			2,639.19
------------------------------------	--	--	-----------------

Report Ref No. CC4/LPC22007608/Epa3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. SNB 4732T

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SNB 4732T

RE-INSPECTION

