



Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462. Tel no. 6631 1188



TOYOTA

Steve (LKK)
18/10/22, 11.30

W 11
P/P
3 d/r
A, B, C

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM LKK 62563561	S1000020 / TPCLAIM	Mdm Wan Mei Kit
	Document No. 0	35 Trevoze Crescent
	Document Date 10/08/2022	Singapore 298049 Mobile: 96882800

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	ZVW40R	AWXEBW S4	25/08/2021	SNB4732T	0	16858	65DS/SNB4732T
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDZS3EU20J067658		2ZRW640320	60	Francis Cher T S	--/--/----	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES T/P INS. : <i>Wongal</i> T/P VEH. : XE1181T ACC DATE : 05.08.22 BY :				/ 50.00
2	B	BP-MECH2 RESET AND REPROGRAMME ECU.				/ 180.00
3	B	BP-LAB2 DRILL HOLE TO INSTALL REVERSE SENSOR.				/ 180.00
4	B	BP-LAB2 CHK REAR WIRING SYSTEM AND CONDUCT WATER TEST.				/ 180.00
5	B	BP-LAB2 REPLACE AND REALIGN REAR BUMPER.				770 900.00
6	B	BP-RES2 SPRAY PAINT ON REAR BUMPER.				590 737.50
7	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION ON REAR BUMPER.				91.59
8	1	T52159-47912 COVER, RR BUMPER / <i>00</i>	1.00	602.60		602.60
9	2	T52023-12240 REINFORCEMENT	1.00	234.70		234.70
10	3	TREVSE-47006 24 BACK SENSOR 1G3 GREY ME	1.00	101.05		101.05

[illegible]

Acknowledged by Repairer
Signature: _____
Date: _____

Customer Copy