



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		Mdm Wan Mei Kit 35 Trevoze Crescent Singapore 298049 Mobile: 96882800		
			Document No. 0				
			Document Date 10/08/2022				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	ZVW40R	AWXEBW S4	25/08/2021	SNB4732T	0	16858	65DS/SNB4732T
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDZS3EU20J067658		2ZRW640320	60	Francis Cher T S	--/--/----		0.00 --/--/----
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY SUNDRIES T/P INS. : T/P VEH. : XE1181T ACC DATE : 05.08.22 BY :				50.00	
2	B	BP-MECH2 RESET AND REPROGRAMME ECU.				180.00	
3	B	BP-LAB2 DRILL HOLE TO INSTALL REVERSE SENSOR.				180.00	
4	B	BP-LAB2 CHK REAR WIRING SYSTEM AND CONDUCT WATER TEST.				180.00	
5	B	BP-LAB2 REPLACE AND REALIGN REAR BUMPER.				900.00	
6	B	BP-RES2 SPRAY PAINT ON REAR BUMPER.				737.50	
7	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION ON REAR BUMPER.				91.59	
8	1	T52159-47912 COVER, RR BUMPER	1.00	602.60		602.60	
9	2	T52023-12240 REINFORCEMENT	1.00	234.70		234.70	
10	3	TREVSE-47006 24 BACK SENSOR 1G3 GREY ME	1.00	101.05		101.05	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total 3,257.44
			Please acknowledge receipt of vehicle		Parts 938.35		GST 7.00% 228.02
					Labour 2,227.50		Less 0.00
					Sublet 91.59		
					Lubrication/Fluid 0.00		
					Others 0.00		Amount Due 3,485.46

Customer Copy