



Borneo Motors

Inchcape

Co. Reg No. : 1967000862
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no. 6631 1188

Sten (LKK)
18/10/22, 11.30a

W 12
P/P
3 d/r
M B L y



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM LKK 6256 3561	S1000020 / TPCLAIM	Mdm Wan Mei Kit
	Document No. 0	35 Trevoze Crescent
	Document Date 10/08/2022	Singapore 298049
		Mobile: 96882800

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	ZVW40R	AWXEBW S4	25/08/2021	SNB4732T	0	16858	65DS/SNB4732T
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTDZS3EU20J067658	2ZRW640320	60	Francis Cher T S	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES T/P INS. : <i>Wongal Ins.</i> T/P VEH. : XE1181T ACC DATE : 05.08.22 BY :				50.00 ✓
2	B	BP-MECH2 RESET AND REPROGRAMME ECU.				180.00 ✓
3	B	BP-LAB2 DRILL HOLE TO INSTALL REVERSE SENSOR.				180.00 ✓
4	B	BP-LAB2 CHK REAR WIRING SYSTEM AND CONDUCT WATER TEST.				180.00 ✓
5	B	BP-LAB2 REPLACE AND REALIGN REAR BUMPER.				770 900.00 ✓
6	B	BP-RES2 SPRAY PAINT ON REAR BUMPER.				590 737.50 ✓
7	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION ON REAR BUMPER.				91.59 ✓
8	1	T52159-47912 COVER, RR BUMPER / 00 1X NN	1.00	602.60		602.60 ✓
9	2	T52023-12240 REINFORCEMENT	1.00	234.70		234.70
10	3	TREVSE-47006 24 BACK SENSOR 1G3 GREY ME 1X NN	1.00	101.05		101.05
		S52161-0K040 PIECE, RR BUMPER NEC	10	4.50		45.00 ✓

For and on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			3,257.44
		Parts 938.35	GST 7.00% 228.02
		Labour 2,227.50	Less 0.00
		Sublet 91.59	
		Lubrication/Fluid 0.00	
		Others 0.00	Amount Due 3,485.46

Acknowledged by Repairer
Signature:
Date:

Customer Copy