

**Borneo Motors**

Attn: Steve

**TOYOTA**

Inchcape

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

3 days Final Bill

TAX INVOICE

Account Details				Account No.	Customer Details			
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia				S1000007 / ICLPI1	Mdm Wan Mei Kit 35 Trevoze Crescent Singapore 298049 Mobile: 96882800			
				Document No. 38067882				
				Document Date 18/11/2022				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2021	ZVW40R	AWXEBW S4	25/08/2021	SNB4732T	11364	16858	65DS/SNB4732T	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTDZS3EU20J067658		2ZRW640320	60	Francis Cher T S	18/10/2022 10.26		18/11/2022	8.27
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES T/P INS. : LONPAC INS. T/P VEH. : XE1181T ACC DATE : 05.08.22 BY : STEVE (LKK)			*			50.00
2	B	BP-MECH2 RESET AND REPROGRAMME ECU.			BP61			180.00
3	B	BP-LAB2 DRILL HOLE TO INSTALL REVERSE SENSOR.			*			180.00
4	B	BP-LAB2 CHK REAR WIRING SYSTEM AND CONDUCT WATER TEST.			*			180.00
5	B	BP-LAB2 REPLACE AND REALIGN REAR BUMPER.			*			720.00
6	B	BP-RES2 SPRAY PAINT ON REAR BUMPER.			BP32			590.00
7	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION ON REAR BUMPER.			0619			91.59
8	1	T52159-47912 COVER, RR BUMPER			1.00	602.60		602.60
9	2	S52161-0K040 PIECE, RR BUMPER			10.00	4.50		45.00
For & on behalf of Borneo Motors (Singapore) Pte Ltd				Customer's Signature		Charge Summary		Total 2,639.19
				Please acknowledge receipt of vehicle		Parts	647.60	GST 7.00% 184.74
						Labour	1,900.00	
						Sublet	91.59	Less 0.00
						Lubrication/Fluid	0.00	
						Others	0.00	
						Amount Due		2,823.93

Company Copy