

ASS. REC. BY:

REF:

AIG/ 2200-7613/Ke

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 80 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: S140 2027 Yr Regn: 10, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: Renault Latitude c.c. 1995Colour N. white / Bl A/C: Insured / Std / NI / NASp. Reading 771320 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VIFI ABL 15AUC 282365Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NI / S/Rim / STD A/Rim orTyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Pailan

Front

R/Bal. 9 mmL/Bal. 9 mmD.O.A. 6/8/22

Rear

R/Bal. 8 mmL/Bal. 8 mmD.O.I. 10/8/2022

Survey held at _____

Des. of Damages: Frt / Rear / OIS / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

11/8 11:30 @ 2650L Canbus

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

) S + RS. \$

) Extras

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD202T**AAD2208-***Not Authorized*
11 Pmg @ 2650/h

Vehicle No.:

Chassis No.:

UEN No:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

10 AUG 2022**SHD202T**

VF1ABL15AUC282365

200303878K

RENAULT

LATITUDE

06/08/2022

SNE7738S/AIG

02/10/2015

PART**LIST**

1 BUMPER COVER REAR	\$	<i>Bu</i> 561.70	✓
1 BUMPER LOWER REAR	\$	<i>Net Wt</i> 411.90	✓
1 BUMPER BRACKET CTR REAR	\$	<i>Sm</i> 98.10	X
1 BUMPER BRACKET SIDE RH REAR	\$	<i>Sm</i> 82.10	X
1 BUMPER RETAINER RH REAR	\$	<i>Sm</i> 59.80	X
1 BUMPER BRACKET SIDE LH REAR	\$	<i>Sm</i> 80.80	X
1 BUMPER RETAINER LH REAR	\$	<i>Sm</i> 54.20	✓
1 BUMPER BEAM REAR	\$	<i>Bz</i> 547.80	✓
1 OUTER PANEL REAR (End Panel)	\$	<i>Bz</i> 745.80	✓
1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>Sm</i> 404.56	X
1 BOOT REAR	\$	<i>R</i> 1,677.20	} X
1 BOOT LOCK	\$	<i>R</i> 246.60	
1 BOOT LOCK CATCH	\$	<i>R</i> 41.70	
1 BOOT FINISHER	\$	<i>Sm</i> 344.70	
1 BOOT WEATHERSTRIP	\$	<i>Sm</i> 178.20	
1 BOOT STRUT LH	\$	<i>Sm</i> 145.10	
1 BOOT STRUT RH	\$	<i>Sm</i> 145.10	
1 BOOT HINGE LH	\$	<i>R</i> 254.20	
1 BOOT HINGE RH	\$	<i>R</i> 254.20	
1 BOOT BADGE 'RENAULT'	\$	<i>nn</i> 82.40	
1 BOOT BADGE	\$	<i>nn</i> 95.80	
	\$	6,511.96	
10%	\$	651.20	
	\$	5,860.76	

Specical Nett

Trans-cab Auto Services Pte Ltd

AAD2208-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD202T

1SET PARKING AID	\$	<i>Pl</i> 700.00	X
1SET REAR BUMPER CLIP	\$	<i>nn</i> 66.00	✓
1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>nn</i> 10.00	X
1SET BUMPER RETAINER RH CLIP RR	\$	<i>nn</i> 20.00	X
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	<i>nn</i> 10.00	X
1SET BUMPER RETAINER CLIP LH RR	\$	<i>nn</i> 20.00	X
1SET BUMPER LOWER REAR CLIP	\$	<i>nn</i> 66.00	✓
1 REAR BOOT STICKER 'Trans-cab'	\$	<i>nn</i> 80.00	X
1 REAR BOOT STICKER '6555-3333'	\$	<i>nn</i> 80.00	X
1 REAR BUMPER ADVERTISEMENT	\$	<i>nn</i> 100.00	X
1 LICENSE PLATE WITH HOLDER REAR	\$	<i>Pl</i> 120.00	X
2 WINDSCREEN SEALANT	\$	<i>nn</i> 150.00	X
1 WINDSCREEN MOULDING	\$	<i>nn</i> 200.00	X
1 WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i> 130.00	X
TOTAL	\$	1,752.00	
TOTAL PARTS	\$	7,612.76	

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>nn</i> 300.00	X
Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	4401
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	6001
To Rust-Proofing Of The Affected Areas.	\$	170.00	301
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00	X
To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00	X

Trans-cab Auto Services Pte Ltd**AAD2208-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD202T

To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i> 170.00	<i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>4</i> 170.00	<i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>4</i> 170.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>4</i> 220.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>201</i>

TOTAL \$ 7,880.00**Over All Total \$ 21,353.53****(LUMP SUM)****Repair Days***20 DAYS**4 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: