

ASS. REC. BY:

REF:

ALG/22007615/KS

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S14D 5978E

Yr Regn:

11.18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Pm

c.c

1798

Colour

M.P. white / RW

A/C:

Insured / Std / NI / NA

Sp. Reading

312251

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB3FU 603075573

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Finanz

Front

Rear

R/Bal.

7

mm

R/Bal.

6

mm

L/Bal.

7

mm

L/Bal.

6

mm

D.O.A.

21/5/22

D.O.I.

10/8/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

17/7

61 Pm @ 1350h

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

close: 20/6

Not Withheld
1/1/2022 @ 1350h

AAD2205-133

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5978E

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

10 AUG 2022

SHD5978E

JTDKB3FU603075573

200303878K

TOYOTA

PRIUS

21/05/2022

GBL3858K/ AIG.

01/11/2018

PART

- 1 COVER, FRONT BUMPER
- 1 FRONT BUMPER SIDE RETAINER RH
- 1 REINFORCEMENT SUB-ASSY, FRONT BUMPER
- 1 ABSORBER, FRONT BUMPER ENERGY
- 1 LAMP ASSY, FOG, RH
- 1 UNIT ASSY, HEADLAMP, RH
- 1 COVER, FRONT BUMPER HOLE, RH
- 1 JAR ASSY, WINDSHIELD WASHER
- 1 GRILLE SUB-ASSY, RADIATOR
- 1 EMBLEM ASSY, RADIATOR GRILLE
- 1 GRILLE, RADIATOR, LOWER NO.1
- 1 FENDER SUB-ASSY, FRONT RH
- 1 LINER, FRONT FENDER, RH
- 1 FRONT FENDER EMBLEM RH

LIST

\$	Bul/cm	516.00	✓
\$	0.17	80.10	✓
\$	n	716.60	x
\$	sn	79.60	x
\$	sn	951.40	✓
\$	sn	2,637.60	x
\$	sn	29.30	x
\$	sn	219.10	x
\$	sn	346.00	x
\$	sn	90.80	x
\$	sn	170.10	x
\$	n	977.80	x
\$	sn	206.70	x
\$	nn	54.60	x

TOTAL \$ 7,075.70

25% \$ 1,768.93

\$ 5,306.78

Special Nett

- 1 FRT BUMPER CLIP
- 1 FRT NUMBER PLATE WITH HOLDER
- 1 FRT BUMPER SIDE RETAINER CLIP
- 1 FENDER LINER CLIP

\$	nn	65.00	✓
\$	sn	120.00	x
\$	nn	65.00	x
\$	nn	75.00	x

TOTAL \$ 325.00

TOTAL PARTS \$ 5,631.78

LABOUR

Trans-cab Auto Services Pte Ltd**AAD2205-133**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5978E

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	nn	250.00	X
Putty And Spray Painting Of The Affected Portion.	\$		1,800.00	22d
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn	380.00	X
To Check Electrical Lighting Concerned.	\$		170.00	20d
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		2,000.00	20d
To check steering geometry and computer wheel alignment	\$	nn	220.00	X
To transfer of rear fender panel fittings, attachment and perform water seepage test.	\$	nn	170.00	X
TOTAL	\$		4,990.00	
Over All Total	\$		10,621.78	

(PART-BY-PART) Repair Days**20 Days****2 days****LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	878K

Vehicle Details

Vehicle No.:	SHD5978E
Vehicle to be Exported:	Yes
Intended Deregistration Date:	10 Aug 2022
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	2ZR2B64334
Chassis No.:	JTDKB3FU603075573
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,605.00
Original Registration Date:	01 Nov 2018
First Registration Date:	01 Nov 2018
Transfer Count:	0
Actual ARF Paid:	\$14,247.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Oct 2026
PARF Rebate Amount:	\$10,685.00

Intended COE Rebate Details

COE Expiry Date:	31 Oct 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$23,736.00
COE Rebate Amount:	\$12,529.00
Total Rebate Amount:	\$23,214.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 10 Aug 2022

OK