

Vehicle Damage Assessment Report for [SMY6064R]

Estimate Created: 11/08/2022 08:04 by LKK_assignments
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 05/02/2023 14:40 by Insurlogic 5 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	India International Insurance	Claim Number
Claim Type	OD	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Toyota	Model	Noah
Engine Type			
License Plate Number	SMY6064R	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- Final review base on information provide by LKK: Concluded the cost of repair at \$5358.55 with 4 days for repair Insurlogic 5 (05/02/2023 14:40)

- Pre Review done base on survey information provided
Take note that this review is done before finalization, a final review on repair cost to be concluded after repair.

Pre Review By : Insurlogic Insurlogic 1 (12/08/2022 03:41)
Amount : \$6042.05
Check: \$80.85
Repair Duration: 4 days

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
FRONT LH FENDER		1	1152.70	-25.00 %	864.53
LH HEADLAMP		1	3606.30	-25.00 %	2,704.73
FRONT BUMPER		1	845.00	-25.00 %	633.75
FRONT BUMPER LH RETAINER		1	99.40	-25.00 %	74.55

Parts Subtotal 4,277.56

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
FRONT BUMPER CLIPS		1.0	50.00	0.00 %	50.00
MISC		1.0	11.00	0.00 %	11.00

Materials Subtotal 61.00

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
REPLACE/ REPAIR ACCIDENT AFFECTED ITEMS AND AREAS	RnR	400.00	0.00 %	400.00
CHECK WIRING	RnR	20.00	0.00 %	20.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
PAINT ON ACCIDENT AFFECTED AREAS	Full spray	600.00	0.00 %	600.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 420.00

Paint Labor Subtotal 600.00

Labor Subtotal 1,020.00

Summary

Repair Cost 5,358.56

Discount(0 %) (0.00)

5,358.56

Excess (0.00)

GST(0.00 %) 0.00

Grand Subtotal	5,358.56
----------------	----------