

Vehicle Number : SKT 5492 U
Vehicle Model : NISSAN QASHQAI
Accident Date : 09.08.2022
Original Reg Date : 15.06.2015

Date : 16.08.2022
Chassis : SJNFEAJ11U1389047
TP Ins. INDIA *Alb.*

Xiao Tong

ESTIMATE

1	1 pc	Front Fender <i>Repis</i>		658.90	+
2	1 pc	Front Fender Arch Garnish <i>ct</i>		483.50	✓
3	1 set	Front Fender Arch Garnish Clip <i>re</i>		30.00	✓
4	1 pc	Front Fender Top Sponge <i>2 pc</i>		65.80	+
5	1 pc	Front Fender Inner Shield <i>2 pc</i>		125.60	+
6	1 set	Front Fender Inner Shield Clip		30.00	+
7	1 pc	Front Door LH <i>Dented</i>		1,245.80	✓
8	1 pc	Front Door Black Sticker LH <i>re</i>		98.60	✓
9	1 pc	Front Door Outer Chrome Moulding LH <i>2 pc</i>		245.30	+
10	1 pc	Front Door Frame Top Chrome Moulding LH <i>re</i>		125.80	+
11	1 pc	Front Door Wing Mirror LH <i>2 pc</i>		698.70	+
12	1 pc	Front Door Outer Handle LH <i>re</i>		185.20	+
13	1 pc	Front Door Outer Handle Joint LH		45.80	+
14	1 pc	Front Door Key Lock LH <i>2</i>		145.20	+
15	1 pc	Front Door Inner Lock LH <i>re</i>		198.50	+
16	1 pc	Front Door Lock Catch LH		57.80	+
17	1 pc	Front Door Weatherstrip LH		178.50	+
18	2 pcs	Front Door Hinge LH <i>2 pc</i>	72.50	145.00	+
19	1 pc	Front Door Checker LH		58.60	+
20	1 pc	Front Door Bottom Protector LH <i>ct</i>		345.80	✓
21	1 set	Front Door Bottom Protector clips LH <i>re</i>		30.00	✓
22	1 pc	Front Door Bottom Rubber LH <i>2</i>		125.60	+
23	1 pc	Front Door Channel LH <i>re</i>		186.40	+
24	1 pc	Front Door Channel Seal LH		72.40	+
25	1 pc	Front Door Regulator Motor w/Gear LH <i>re</i>		564.20	+
26	1 pc	Front Door Inner Trim LH <i>2 pc</i>		1,869.50	775
27	1 set	Front Door Inner Trim Clip LH <i>2 pc</i>		30.00	✓
28	1 pc	Front Door Speaker LH <i>re</i>		158.60	+
29	1 pc	Rear Door LH <i>Repis</i>		1,205.60	+
30	2 pcs	Rear Door Black Sticker LH <i>re</i>		58.30	+
31	1 pc	Rear Door Outer Chrome Moulding LH <i>2 pc</i>		188.90	+
32	1 pc	Rear Door Frame Top Chrome Moulding LH <i>re</i>		125.60	+
33	1 pc	Rear Door Outer Handle LH <i>2</i>		145.80	+
34	1 pc	Rear Door Outer Handle Joint LH <i>re</i>		45.60	+
35	1 pc	Rear Door Inner Lock LH <i>re</i>		198.60	+
36	1 pc	Rear Door Lock Catch LH		65.30	+

37	1 pc	Rear Door Weatherstrip LH		186.30	+
38	2 pcs	Rear Door Hinge LH	70.60	141.20	+
39	1 pc	Rear Door Checker LH		49.60	+
40	1 pc	Rear Door Bottom Protector LH		345.90	+
41	1 set	Rear Door Bottom Protector clips LH		30.00	+
42	1 pc	Rear Door Bottom Rubber LH		105.60	+
43	1 pc	Rear Door Channel LH		189.30	+
44	1 pc	Rear Door Channel Seal LH		75.60	+
45	1 pc	Side rocker panel		785.30	+
46	1 pc	Rear Fender LH		1,245.60	+

47 1pc Rear Fender Arc Garnish. at 456.10 subtotal 13,393.20
 48 1set Rear Fender Arc Garnish clips. 30.00 Less 10% 1,339.32
 Total 12,053.88

3940.70

3546.63

Labour charge

Panel Beating	1,600.00	300
Spray painting	1,600.00	400
Anti rust	150.00	30
Remove and install front door mechanism	150.00	80
Remove and install rear door mechanism	150.00	+

Total

\$ 15,703.88

810

Adrian Lj
 L/S 17/08/22
 03 Days

Label: 4356.63

L/S: 3.4K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

3.4K