

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0665/2022/EQ
DATE : 6-Aug-22
WIP : 36236

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 10/8/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS. TEE GEOK CHENG
ADDRESS : 308B ANG MO KIO AVE 1
#07-401
SINGAPORE 562308
TELEPHONE : HP +65 93864523
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210085013-01
VEHICLE NO : SLU 9009 P
MODEL CODE : AUDI A4 2.0 TFSI S-TRONIC
MODEL YEAR : 30/7/2021
ENGINE NO : DEM 028171
CHASSIS NO : WAUZZZF4XMA021527
MILEAGE : 21,807 KM
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 4-Aug-22
PLACE OF ACCIDENT : ALONG TELOK KARAN ROAD TOWARDS CHANGI
DIRECTION IMMEDIATE AFTER ST PATRICK'S ROAD

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLU 9009 P

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	250 ✓
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.	S/N \$ 1,400.00	✓
4	TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$ 1,200.00	✓
5	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY FOR RHS FRONT DOOR.	S/N \$ 280.00	✓
6	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, RHS FRONT FENDER AND RHS HEADLIGHT. TO REPAIR RHS FRONT FENDER TOP SUPPORT AND RHS FRONT DOOR. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,600.00	1750 + 1500 = 3250 ✓
SUB-TOTAL LABOUR CHARGES		6.5 : \$ 9,310.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLU 9009 P

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO RESPRAY FRONT BUMPER, BONNET, RHS FRONT FENDER, RHS FRONT FENDER TOP SUPPORT AND RHS FRONT DOOR. <i>1/2 d Fin Fill R4</i>	S	4,500.00	2470 ✓
8	TO RENEW RHS FRONT RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N S	520.00	✓
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N S	192.00	✓
TOTAL LABOUR CHARGES		: S	14,522.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 9009 P

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER / BR	1	\$	2,377.00 / 1901.60	
2	FRONT BUMPER FIXING PARTS X nn	1	\$	393.00	
3	FRONT BUMPER SECURING STRIP - BT	21	\$	79.00 / 63.20	
4	FRONT BUMPER GRILLE - CENTER ? X nn	1	\$	219.00	
5	FRONT BUMPER CLOSING ELEMENT ? / BR	1	\$	293.00 / 234	
6	FRONT BUMPER AIR GUIDE - RH ? / CRV	1	\$	51.00 / 40.08	
7	FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE 1 X nn	1	\$	293.00	
8	FRONT BUMPER AIR GUIDE GRILLE - RH / ms	1	\$	151.00 / 120.40	
9	FRONT BUMPER AIR GUIDE GRILLE TRIM - RH / cy	1	\$	54.00 / 42.64	
10	RADIATOR GRILLE ? X nn	1	\$	1,754.00	
11	FRONT BUMPER GUIDE SECTION - RH / BR	1	\$	41.00 / 32.24	
12	FRONT BUMPER FOAM FILLER PIECE ? / BR	1	\$	212.00 / 169.20	
13	FRONT BUMPER CARRIER ? / BR BT	1	\$	899.00 / 719.20	
14	FRONT BUMPER BRACKET - RH ? X nn	1	\$	254.00	
15	FRONT BUMPER TOP COVER / BR	1	\$	143.00 / 114	
16	CAUTION SIGN STICKER / M	1	\$	16.00 / 12.40	
17	AIR CONDITIONER STICKER / M	1	\$	9.00 / 6.64	
18	FRONT BUMPER BRACKET / BR	1	\$	154.00 / 122.80	
19	FRONT BUMPER SUPPORT - LH / RH ? / nec	2	\$	64.00 / 51.04	
20	POP RIVET ? / nec	4	\$	4.00 / 2.88	
SUB TOTAL SPARE PARTS		:	\$	7,460.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 9009 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT PARKING AID SENSOR - INNER / OUTER ? x nn	2	\$ 532.00	
22	FRONT PARKING AID SEAL RING ✓ x nn	4	\$ 10.00	
23	FRONT BUMPER WIRING SET ? x nn	1	\$ 642.00	
24	HORN LOW TONE - RH ? x nn	1	\$ 139.00	
25	FRONT SPRING SHACKLE - RH ? x nn	1	\$ 33.00	
26	FRONT FENDER - RH ✓ nn	1	\$ 1,227.00	981.60
27	FRONT FENDER ATTACHMENT PARTS x nn	1	\$ 225.00	
28	FRONT FENDER CLOSING ELEMENT - RH ✓ nk	1	\$ 81.00	64.24
29	FRONT FENDER BRACKET - RH ✓ BT	1	\$ 41.00	32.72
30	FRONT FENDER BRACKET - RH ? x nn	1	\$ 55.00	
31	POP RIVET ✓ nk	7	\$ 27.00	21.28
32	FRONT FENDER BRACKET - RH ? x nn	1	\$ 36.00	
33	FRONT FENDER BRACE - RH ? / BT	1	\$ 132.00	105.20
34	FRONT FENDER WHEEL HOUSING LINER - RH ✓ CR	1	\$ 262.00	209.60
35	FRONT AND REAR WHEEL HOUSING LINER ATTACHMENT PARTS ✓ nk	1	\$ 149.00	119.20
36	FRONT WHEEL SPOILER - RH ✓ CR	1	\$ 82.00	65.12
37	FRONT WHEEL SPOILER TRIM - RH x / BR	1	\$ 40.00	32.00
38	FRONT FENDER TOP COVER - RH ✓ nk	1	\$ 35.00	27.52
39	HEADLAMP COVER - RH ✓ BR	1	\$ 49.00	38.64
40	BONNET ✓ nn	1	\$ 3,425.00	2740
SUB TOTAL SPARE PARTS		:	\$ 7,222.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 9009 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	BONNET ATTACHMENT PARTS <i>X nn</i>	1	\$ 431.00	
42	BONNET HINGE - LH / RH <i>? X nn</i>	2	\$ 680.00	
43	BONNET IMPACT PROTECTION - CENTER / LH / RH <i>mc</i>	3	\$ 93.00	<i>73.20</i>
44	FRONT FENDER INNER COVER - RH <i>? X nn</i>	1	\$ 68.00	
45	BONNET STRIKER - RH <i>? X nn</i>	1	\$ 56.00	
46	BONNET LOCK <i>? X nn</i>	1	\$ 228.00	
47	BONNET BOWDEN CABLE - CENTER <i>? X nn</i>	1	\$ 64.00	
48	BONNET BOWDEN CABLE COVER <i>? X nn</i>	1	\$ 11.00	
49	BONNET BOWDEN CABLE <i>? X nn</i>	1	\$ 64.00	
50	BONNET RELEASE LEVER <i>? X nn</i>	1	\$ 15.00	
51	HEADLIGHT - RH <i>BR</i>	1	\$ 8,172.00	<i>6537.60</i>
52	HEADLIGHT HOSE <i>? X nn</i>	1	\$ 42.00	
53	HEADLIGHT COMPENSATING PIECE <i>? / mrs</i>	(3)	\$ 137.00	<i>108</i>
54	LIFT CYLINDER - RH <i>BR</i>	1	\$ 231.00	<i>184.40</i>
55	LIFT CYLINDER BRACKET <i>BR</i>	1	\$ 7.00	<i>5.44</i>
56	LIFT CYLINDER CORRUGATED PIPE - LONG <i>? X nn</i>	1	\$ 107.00	
57	LIFT CYLINDER CORRUGATED PIPE - SHORT <i>? X nn</i>	1	\$ 53.00	
58	LOCK CARRIER <i>? / BR</i>	1	\$ 1,127.00	<i>901.60</i>
59	RADIATOR COOLANT REGULATOR SUPPORT - RH <i>? X nn</i>	1	\$ 43.00	
60	AIR COOLER CHARGE <i>? X nn</i>	1	\$ 654.00	
SUB TOTAL SPARE PARTS		:	\$ 12,283.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 9009 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	AIR COOLER CHARGE PRESSURE HOSE - RH <i>2 x nn</i>	1	\$ 413.00	
62	A/C CONDENSER <i>2 x nn</i>	1	\$ 683.00	
63	TEMP SENSOR BRACKET <i>2 / nec</i>	1	\$ 21.00	16.32
64	RADIATOR <i>2 x nn</i>	1	\$ 1,013.00	
65	COOLANT <i>2 / nec</i>	6	\$ 297.00	237.12
66	RADIATOR AIR GUIDE - RH <i>2 x nn</i>	1	\$ 51.00	
67	RADIATOR AIR GUIDE - LH / RH / UPPER <i>2 x nn</i>	3	\$ 57.00	
68	RADIATOR AIR GUIDE - LOWER <i>2 x nn</i>	1	\$ 25.00	
69	INTAKE AIR DUCT - RH <i>2 x nn</i>	1	\$ 25.00	
70	INTAKE AIR DUCT GUIDE <i>2 x nn</i>	1	\$ 61.00	
71	INTAKE AIR DUCT HOSE <i>2 x nn</i>	1	\$ 110.00	
72	INTAKE AIR DUCT FILTER <i>2 / BE</i>	1	\$ 418.00	334.40
73	AIR MASS METER <i>2 x nn</i>	1	\$ 629.00	
74	FRONT WHEEL ALUMINIUM RIM <i>cut</i>	1	\$ 1,292.00	1033.60
75	RUBBER VALVE <i>As x nn</i>	1	\$ 4.00	
76	FRONT WINDOW TRIM STRIP CHROME - RH <i>x nn</i>	1	\$ 344.00	
77	FRONT WINDOW TRIM STRIP GUIDE HIGH CHROME <i>x nn</i>	1	\$ 287.00	
78	FRONT NO PLATE <i>2 x nn</i>	S/N	\$ 60.00	
79	SUNDRIES <i>2 / nec</i>		\$ 500.00	304.96
TOTAL SPARE PARTS			: \$	33,255.00
TOTAL LABOUR CHARGES			: \$	14,522.00
GRAND TOTAL			: \$	47,777.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

*Stew (LKK)
10/8/22, 3:00pm*

*ON. ✓
EXC - 7
6 + 7 days = 13 days
Supr P/P
by Bar y*

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT