

TP China
Ashes.

SME 1982D.
Honda Vezel Hybrid
RU37317411.

Front Bumper	Rehd	765.40	✓
Front Bumper Clips.	per	30(SN)	✓
Front Bumper Side Holder x 2	LH cracked	34.20	✓
Front Bumper Lower Garnish.	Revis	381.50	+
Front Bumper Reinforcement.	xp m	321.60	+
Front Bumper Fog Lamp LH	xp m	327.70	+
Front Bumper Fog Lamp Cover LH.	torn	92.50	✓
Hendup LH	Cracked.	1850.50	✓
Hendup Lower Bracket LH.	Cracked	55.60	✓
Front LH Fender Arc Garnish	Revis	205.60	+
Front LH Fender Arc Garnish Clips.	men	20(SN)	+
Front LH Wheel Rim	At	700(SN) 400	
Front LH Lower Arm.	} xp m	425.60	+
Front LH Knuckle Arm.		405.80	✓

SME 1982D.

Front LH Wheel Hub c/w Bearing $\int$ 245.50

Front LH Shock Absorber - $\int$ 351.50

Air Resonator Tank.

X4
~

180.50 +

279820 S.N. 430

223856

Panel Beating

Spry Painting.

Wiring.

To spray full coat.

To dismantle front undercarriage

To perform wheel alignment.

~~700~~ 300

~~600~~ 400

~~50~~ 30

150 +

320 +

150 +

730

total: 3398.56

L/S: 2.7K

03 Days.

(2,700)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: