

Tropical Tech Automobile Services

BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M/s : **MSIG Insurance (Singapore) Pte. Ltd**
4, Shenton Way, #21-01, SGX Centre 2,
Singapore 068807

Attn : Motor Claims Department
Tel : 68272888
Fax : 68277800

Estimate bill : TT 28 / 22 / TP / WT

Registration No : GBE751R

Make / model : Kia K2500 Lorry

Mileage :

Date : 26 / 08 / 2022

**TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO: GBJ5099G AND GBE751R ALONG
AYE HIGHWAY NEAR CLEMENTI EXIT ON 05 AUGUST 2022 AT ABOUT 1024HRS.**

1pc	Rear gate	1150	\$	1,889.00	✓
1pc	Rear gate '70km/h' sticker		\$	11.00	✓
1pc	Rear gate '13 pax' sticker		\$	11.00	✓
2pcs	Rear gate hinge		\$	432.00	X
2pxs	Rear tail lamp	0155	\$	594.00	✓
2pxs	Rear tail lamp panel	0155	\$	486.00	✓
1set	Rear reversing sensor		\$	360.00	2001n
	Sub A total :		\$	3,783.00	
	Less 20% discount :		\$	756.60	
	A total :		\$	3,026.40	

Special net items :

1pc	Rear license smart plate & casing	\$	35.00	✓
	B total :	\$	35.00	

Remove and transfer rear gate necessary attachment spart part items.

Remove and refit rear gate, rear gate hinges, rear tail lamps, rear tail lamp panels, rear reversing sensors.

Heat / weld / beating / pull / straighten / align rear chassis frame by Chassis Alignment jack.

Diagnostic and reset rear reversing sensor fault error by HHT

To check and refit rear tail lamp wiring harness.

Under coating on rear damaged portion.

Putty / primer application, spray painting rear gate, rear gate hinges, rear tail lamp panels, rear bumper reversing sensors.

Grand final amount :

\$ 4,591.40

Tropical Tech Automobile Services



(Authorised Signature)
William Tan

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: