

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 25 Oct 2022

Preliminary Advice

Insured Vehicle No	: GBJ5099G	Accident Date	: 05/08/2022
TP Vehicle No	: GBE751R	Assignment Date	: 11/08/2022
Make	: KIA K2500 6M/T	Est. Duration of Repair	: 3
Date of Inspection	: 07/09/2022		
Inspection At	: TROPICAL SUCCESS AUTO CARE (HQ) BLK 5032 ANG MO KIO AVENUE 3, #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,591.40
Revised Amount	:S\$	2,441.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,441.00
 Lump Sum Repair	 :S\$	 1,900.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 () Part-by-Part repair
 (X) Lump Sum repair
- (X) The above survey was conducted on a 'without prejudice' basis. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.