

XIN HUA WORKSHOP PTE LTD

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933

Reg : 201838521G

Vehicle Number : SJR5499Z
Vehicle Model : KIA CERATO FORTE
Accident Date : 10.08.2022
Original Reg Date : 29.06.2009

Date : 10.08.2022

Chassis : KNAFH221395086838

TP Ins. AIG Xiao Tong

ESTIMATE

1	1 pc	Bonnet <i>Dented</i>		908.60	✓ 788
2	1 pc	Bonnet Inner Lock <i>3 N/P</i>		125.60	+
3	1 pc	Bonnet Lock Cable <i>1 New</i>		85.00	+
4	2 pcs	Bonnet Hinges	65.80	131.60	+
5	1 pc	Front Bumper <i>Distorted</i>		705.80	✓ 562
6	1 pc	Front Bumper Side Retainers <i>LH Dented</i>		68.90	35
7	1 set	Front Bumper Clips <i>New</i>		50.00	30
8	1 pc	Front Bumper Reinforcement <i>New</i>		345.80	+
9	1 pc	Front Bumper Sponge <i>crushed</i>		185.60	✓ 120
10	1 pc	Front Bumper Lower Grille <i>New</i>		105.80	+
11	1 pc	Front Bumper Number Plate Base <i>New</i>		85.20	+
12	1 pc	Front Bumper Fog Lamps <i>crushed</i>		198.60	✓
13	1 pc	Front Bumper Fog Lamps Cover <i>crushed</i>		98.70	✓
14	1 pc	Front Grille <i>New</i>		345.80	+
15	1 pc	Front Grille Chrome Moulding <i>New</i>		168.90	+
16	1 pc	Front Grille Badge <i>3 N/P</i>		48.00	+
17	1 set	Front Grille Clips <i>1 New</i>		38.00	+
18	1 pc	Headlamps <i>crushed</i>		508.90	✓
19	1 pc	Headlamps Bottom Retainers <i>New</i>		85.90	+
20	1 pc	Front Wiper Garnish Side Rubber <i>New</i>	45.80	91.60	+
21	1 pc	Front Fender <i>Reis</i>		398.70	+
24	1 pc	Front Fender inner cowling <i>New</i>		165.20	+
25	1 pc	Support Panel <i>crushed</i>		569.80	✓
26	1 pc	Brace Panel <i>New</i>		78.90	+
27	1 pc	Horns <i>3 N/P</i>		120.00	+
28	1 pc	Radiator <i>3 N/P</i>		792.00	+
29	1 pc	Air Con Condenser <i>1 New</i>		852.00	+

subtotal 8,156.30

Less 10% 815.63

total 7,340.67

2911
2619.90

Special Nett

1	1 pc	Front Number Plate with Cover <i>NPM</i>		50.00
2	1 pc	Radiator Coolant <i>N</i>		80.00

40

Labour charge

Panel Beating		1,600.00
Spray painting		1,600.00
Check Wiring on headlamp		100.00
Anti rust		180.00
Remove and install air con		150.00

\$ 11,100.67

1380

Adrian Li

4/s. 10/08/22.

05 Days.

total: 4039.90

4/s: 3.2K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: