

FASTECH AUTO PTE LTD  
 1 Kaki Bukit Ave 6 #01-48 Autobay  
 Singapore 417883  
 Tel No: 67452063/ 67467158 Fax No: 67458520  
 Tax Reg No : 200006262D

U/S 18,000

not Allowed  
 all  
 11/8/22  
 U/S \$18,000  
 4 days.

VEHICLE No: SLE 7197B

NETT ITEM

QTY	DESCRIPTION	REMARKS	UNIT PRICE	TOTAL PRICE	STATUS
1PC	BONNET	Beaf/3uc	1800	\$2,055.00	/
1PC	BONNET INNER CENTRE SEAL	Toin	115	\$182.00	/
2PCS	BONNET HINGES @\$ 380.00	Beaf/Twl	300x2=600	\$760.00	/
1PC	BONNET INSULATOR	17		\$380.00	X
1SET	BONNET INSULATOR CLIPS	all	60	\$80.00	/
1PC	BONNET INNER LOCK	Twl	225	\$650.00	/
1PC	BONNET LOCK CABLE	17		\$220.00	X
1PC	FRONT BUMPER	Dus	1350	\$2,297.00	/
2PCS	FRONT BUMPER SIDE RETAINERS @\$250.00	one/Beaf	115	\$500.00	/
1PC	FRONT BUMPER CENTRE GRILLE	Toin	245	\$420.00	/
1PC	FRONT BUMPER LOWER CENTRE GRILLE	Toin	195	\$399.00	/
1PC	FRONT BUMPER SPONGE	Toin	182	\$416.00	/
1PC	FRONT BUMPER REINFORCEMENT	Beaf	635	\$1,115.00	/
1PC	FRONT BUMPER REINFORCEMENT LOWER BRACKET	Twl	302	\$350.00	/
1PC	FRONT BUMPER DAY LIGHT LAMP NLS	Beaf/mul	380	\$1,100.00	/
1PC	FRONT BUMPER UNDER COVER	Toin	320	\$880.00	/
1SET	FRONT BUMPER UNDER COVER CLIPS	all	45	\$60.00	/
1PC	FRONT BUMPER STIFFENER N/S	Dus		\$90.00	/
1PC	FRONT BUMPER FINISHER N/S	Dus	115	\$135.00	/
1PC	FRONT FOG LAMP N/S	Beaf	395	\$520.00	/
1PC	FRONT FOG LAMP GARNISH N/S	Toin	188	\$335.00	/
1PC	FRONT BUMPER TOP RUBBER	Toin	102	\$120.00	/
1PC	FRONT BUMPER TOP RETAINER	Dus	165	\$182.00	/
1PC	FRONT GRILLE ASSY	one	785	\$980.00	/
1SET	FRONT GRILLE PARKING CAMERA	17		\$1,850.00	X
1PC	FRONT SIGNAL LAMP N/S	one	230	\$245.00	/
2PCS	HEADLAMPS @\$4928.00	NLS Beaf	3066	\$9,856.00	1PC
2PCS	HEADLAMP LOWER BRACKETS @\$250.00	NLS one	145	\$500.00	1PC
1PC	HEADLAMP NOZZLE COVER N/S	NF		\$82.00	X
1PC	HEADLAMP NOZZLE N/S	NF		\$350.00	X
1PC	FRONT AIR GUIDE TOP N/S	Toin		\$98.00	/
2PCS	FRONT AIR GUIDES @\$ 430.00	NLS Toin	300	\$870.00	1PC
1PC	FRONT SUPPORT PANEL TOP COVER	Dus	192	\$199.00	/
1PC	FRONT SUPPORT PANEL	Dus	1560	\$1,955.00	/
1PC	FRONT SUPPORT LOWER PANEL N/S	Dus	152	\$200.00	/
1PC	FRONT SUPPORT PANEL CENTRE BRACKET	Twl	100	\$150.00	/
1PC	AIR CON CONDENSER	Beaf/Twl	1480	\$1,540.10	/
1PC	RADIATOR	Beaf		\$1,988.00	X
1PC	INTER COOLER	17		\$1,450.00	X
1PC	FRONT BRACE PANEL	17		\$885.00	X
1PC	FRONT FENDER N/S	Dus		\$1,200.00	/

(102) 820

1PC	FRONT FENDER INNER SHIELD N/S	Torn	245	\$313.00	/
1PC	FRONT FENDER INNER SHIELD CLIPS N/S	neu		\$50.00	/
1PC	FRONT FENDER INNER TOP GARNISH N/S	Torn	164	\$165.00	/
1PC	FRONT DOOR N/S	R		\$2,880.00	X
1PC	WASHER TANK NECK	DE	105	\$145.00	/
1PC	WASHER TANK	Dis	230	\$288.00	/
1PC	WASHER TANK MOTOR	JM	205	\$280.00	/
1SET	FRONT BUMPER CLIPS	neu	60	\$80.00	/
1PC	FRONT LICENCE PLATE W/HOLDER	11		\$150.00	X
2PCS	FRONT PDC SENSORS @\$220.00	11's shorted	195	\$440.00	1PC
1PC	FRONT DISTANCE SENSOR N/S	short	195	\$250.00	/
1BOL	AIR CON OIL	neu		\$50.00	/
1BOL	RADIATOR COOLANT	neu		\$50.00	/
1PC	ROCKER PANEL GARNISH N/S	Torn	820	\$988.00	/
1SET	ROCKER PANEL GARNISH CLIPS N/S	neu		\$50.00	/
1PC	FRONT SHOCK ABSORBER N/S	See		\$845.00	X
1PC	FRONT LOWER ARM N/S	Best	600	\$755.00	/
1PC	FRONT KNUCKLE ARM N/S	Wagon	895	\$920.00	/
1PC	FRONT KNUCKLE ARM BEARING N/S	Dodge	380	\$450.00	/
1PC	FRONT DRIVE SHAFT N/S	11		\$1,180.00	X
2PCS	FRONT ENGINES @\$450.00	11		\$900.00	X
1PC	FRONT ENGINE REAR	11		\$380.00	X
1PC	FRONT SPORT RIM N/S	wrapped	1100	\$1,200.00	/
				\$50,453.10	

TO CHECK WIRING	\$50.00	30
TO REFILL AIR CON GAS	\$120.00	100
TO DISMANTLE & REPLACED FRONT PDC SENSOR	\$80.00	50
TO CONDUCT WHEEL ALIGNMENT	\$120.00	100
TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE	\$350.00	120
TO SPRAY RUST PROOFING	\$100.00	60
TO RESET DIAGNOSTIC & REPROGRAMME SYSTEM	\$580.00	60
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,500.00	1000
TO PUTTY & SPRAY PAINTING	\$1,800.00	1300
TOTAL	\$55,153.10	

P-21946  
 102  
 19751.4  
 2820  
 22571.4  
 18057

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: