

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST 201001188E (R.C.B No) 2010011581

GBC 6470Y

TP/MSIG

M/S : MSIG INSURANCE (S) PTE LTD (SGX)
16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581

TEL: 68277660 FAX: 62257402
ATTN: Motor Claim Department

WS Ref: TP/MSIG
Claim Type: Third Party
Accident Date: 10/08/2022
TP Veh Reg No: GBK8269H

Estimate No: ES2290801/YISHUN
Date: 11 Aug 2022
Policy No: DMCG22007562
Veh Reg No: GBC6470Y
Make/Model: TOYOTA HIACE
MANUAL
Chassis No: JTFHT02P100117209
Engine No: 1KD2299810
Reg. Date: 20/06/2013

Not Authorized

11 Reg & 47002

Repair After Rain

6 days

Estimate Repair Cost to Vehicle No :GBC6470Y

Description	U/Price	Quantity	List Price	Amount
List Price			SS	SS
1 REAR BUMPER	397.20	1 PC	397.20	✓
2 REAR BUMPER SIDE RETAINERS	22.80	2 PCS	45.60	✓ 22.80
3 REAR BUMPER CLIPS	3.80	6 PCS	22.80	✓
4 REAR TAILGATE	2,154.20	1 PC	2,154.20	✓
5 TAILGATE LOGO	66.70	1 PC	66.70	✓
6 TAILGATE STICKER (TOYOTA HIACE)	52.60	1 PC	52.60	✓
7 TAILGATE OUTER HANDLE	143.10	1 PC	143.10	✓
8 TAILGATE INNER LOCK	323.60	1 PC	323.60	✓
9 TAILGATE INNER RUBBER	381.90	1 PC	381.90	✓
10 REAR WINDSCREEN GLASS	1,297.10	1 PC	1,297.10	✓
11 REAR END PANEL OUTER	309.80	1 PC	309.80	✓
12 REAR END PANEL TOP BEAM	114.30	1 PC	114.30	✓
13 RH TAILLAMP	324.70	1 PC	324.70	✓
14 REAR NUMBER PLATE LAMP	79.50	1 PC	79.50	X
15 REAR ROOM MIRROR	524.10	1 PC	524.10	X
16 REAR NUMBER PLATE	20.00	1 PC	20.00	✓
17 STICKER - 70KM/H	10.00	1 PC	10.00	✓
18 REAR WINDSCREEN GLASS GUM	40.00	1 PC	40.00	✓
19 REVERSE SENSOR	200.00	1 SET	200.00	✓
Sub Total			6,331.35	
Less 25%			1,582.84	4,748.51
Special Net				
16 REAR NUMBER PLATE	20.00	1 PC	20.00	✓
17 STICKER - 70KM/H	10.00	1 PC	10.00	✓
18 REAR WINDSCREEN GLASS GUM	40.00	1 PC	40.00	✓
19 REVERSE SENSOR	200.00	1 SET	200.00	✓
Sub Total			270.00	270.00

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374-382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST: 201001158F RCB NO: 201001158F

M/S : MSIG INSURANCE (S) PTE LTD (SGX)
16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581
TEL: 68277660 FAX: 62257402
ATTN: Motor Claim Department

WS Ref: TP/MSIG
Claim Type: Third Party
Accident Date: 10/08/2022
TP Veh Reg No: GBK8269H

Estimate No: ES2290801/YISHUN
Date: 11 Aug 2022
Policy No: DMCG22007562
Veh Reg No: GBC6470Y
Make/Model: TOYOTA HIACE
MANUAL
Chassis No: JTFHT02P100117209
Engine No: 1KD2299810
Reg. Date: 20/06/2013

Estimate Repair Cost to Vehicle No :GBC6470Y

Description	U/Price	Quantity	List Price	Amount
Labour			S\$	S\$
20 REMOVE AND REFIX REAR WINDSCREEN GLASS	100.00	1 LA	100.00	✓
21 REMOVE & REFIX REAR BUMPER ASSY, TAILGATE, LOCK ASSY, TAILLAMP, TO CUT, WELD & RENEW REAR END PANEL OUTER, KNOCK & REPAIR REAR FLOOR BOARD PANEL AND REALIGN THE SAME	700.00	1 LA	700.00	600
22 PUTTY & RESPRAY ON REAR END PANEL, REAR FLOOR BOARD PANEL, TAIL GATE, LOWER GARNISH	600.00	1 LA	600.00	500
23 TO REWRITE ADVERTISEMENT	300.00	1 LA	300.00	200
			1,700.00	1,700.00
			Total	S\$ 6,718.51
			Add GST @ 7%	470.30
			Total Amount Payable	S\$ 7,188.81

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Parts \$5704.95
Supp \$324.70
\$6029.65
25% 1507.41
\$4522.24
270 SN
1400
\$6192.24
4% \$4950.1