

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKM 886L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR FENDER RH	DENTED	4,324.40	4,324.40
4	BLIND RIVET SCREW	NECESSARY	23.20	23.20
1	STONEGUARD FILM (RH)	NECESSARY	130.00	130.00
1	REAR WINDSCREEN GLASS	NECESSARY	1,754.60	1,754.60
8	RIVET	NECESSARY	16.80	16.80
8	CLIP	NECESSARY	52.00	52.00
			6,301.00	6,301.00
	SPECIAL NETT ITEMS			
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
			50.00	20.00
	<u>LABOUR</u>			
	TO REMOVE/REPLACE REAR FENDER RH & ALL ACCIDENT DAMAGED BODY PARTS. TO REPAIR ALL AREAS AFFECTED BTY THE ACCIDENT.		6,240.00	5,460.00
	TO RESPRAY REAR FENDER RH.		1,500.00	1,100.00
	TO SUPPLY TEROSTAT SEALANT ON THE CUTTING AREAS.		350.00	250.00
	TO CARRY-OUT BODY CAVITY PRESERVATION.		250.00	150.00
	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.		500.00	250.00
	TO SUPPLY 1 PC BODY CHASSIS STICKER & 1 PC TIRE PLATE STICKER.		300.00	300.00
	TO REMOVE & REPLACE THE REAR WINDSCREEN GLASS.		560.00	560.00
	TO SUPPLY SEALER ON THE REAR WINDSCREEN GLASS.		195.00	195.00
	TO SUPPLY SOLAR FILM ON THE REAR WINDSCREEN GLASS.		300.00	300.00
	TO SUPPLY / INSTALL THE PAINT PROTECTION FILM STICKER. (PRICE TO BE ADVISE) (NPA)		-	-
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	150.00

Report Ref No. CS/FTC22007631/Eqcm4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		600.00	600.00
			11,045.00	9,315.00
	GRAND TOTAL		17,396.00	15,636.00
	RECOMMENDED COST OF REPAIRS			15.636.00

Report Ref No. CS/FTC22007631/Eqcm4



Automotive Assessor

X.S.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.