



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FORTISCOR ADJUSTERS PTE LTD 3 PHILIP STREET #09-03 ROYAL GROUP BUILDING SINGAPORE 048693			Ref: CS/FTC22007631/Eqcm4 Date: 15/08/2022 Code: FTC	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SKM 886L	
Policy No.	FCA2200861AM	Coverage (\$)	0.00	
Claim No.	280709 PL (E)	Excess (\$)	0.00	
Assign From	MUHAMMAD ASIF	Assign Date	11/08/2022	
2. Vehicle Particulars & Condition				
Make & Model	PORSCHE 911	c.c	2981	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WP0ZZZ99ZHS116484	Colour	BLUE	
Odometer	26975 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/35 ZR20	MICHELIN	5 mm	
L/H Front Tyre	245/35 ZR20	MICHELIN	5 mm	
R/H Rear Tyre	245/35 ZR20	MICHELIN	5 mm	
L/H Rear Tyre	245/35 ZR20	MICHELIN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/07/2022	Inspection Date	10/08/2022	
Survey held at	27A TANJONG PENJURU SINGAPORE 609042			
Repairer	EUROKARS HABITAT PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	