

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0658/2022/EQ  
**DATE** : 4-Aug-22  
**WIP** : 36034

**VEHICLE NOT IN WORKSHOP. SURVEY TBC.**

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

**Tel: 6880 4602 - Fax: 6880 4838**

**OWNER'S NAME** : MS. YUM LIN FOON  
**ADDRESS** : 27 HAZEL PARK TERRACE  
#11-05  
SINGAPORE 678949  
**TELEPHONE** : HP +65 98763112  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** : 2070135153  
**VEHICLE NO** : **SMV 1960 C**  
**MODEL CODE** : AUDI Q3 SPORTBACK 1.4 TFSI  
**MODEL YEAR** : 18/9/2020  
**ENGINE NO** : CZD C00162  
**CHASSIS NO** : WAUZZZF35L1124327  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 2-Aug-22  
**PLACE OF ACCIDENT** : PIE AFTER WHITLEY ROAD EXIT TOWARDS TUAS

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

### ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMV 1960 C

| S/N                         | NATURE OF JOBS                                                                                                                                                                      | ESTIMATED CHARGES     | SURVEYOR'S RECOMMENDATIONS                                                                   |
|-----------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------|----------------------------------------------------------------------------------------------|
| 1                           | TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR.                                                                                                                  | S/N \$ 360.00         | X                                                                                            |
| 2                           | TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.                                                          | S/N \$ 800.00         | 560.                                                                                         |
| 3                           | TO DISMANTLE AND REINSTALL REAR BUMPER. TO REPAIR RHS REAR FENDER. TO RENEW RHS REAR DOOR AND RHS FRONT DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | \$ 3,500.00           | 1500.                                                                                        |
| 4                           | TO RESPRAY REAR BUMPER, RHS REAR FENDER, RHS REAR DOOR, RHS FRONT DOOR, 2 DOOR COVERS AND BOTH REAR WHEEL ARCH TRIMS.                                                               | \$ 5,500.00           | 2450.<br>550 x 5 = 1650.<br>Door Cover x 2 = 200 x 2 = 400<br>Wheel Arch x 2 = 200 x 2 = 400 |
| 5                           | TO CARRY OUT DIAGNOSTIC CHECK                                                                                                                                                       | S/N \$ 192.00         | ✓                                                                                            |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                                                     | <b>: \$ 10,352.00</b> | 2450.                                                                                        |

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 1960 C**

|                             |                                               |     | DAMAGED PARTS & PRICES |         |
|-----------------------------|-----------------------------------------------|-----|------------------------|---------|
| S/N                         | PARTS DESCRIPTION                             | QTY | S/NETT                 | REMARKS |
| 1                           | REAR DOOR - RH <i>Dented</i>                  | 1   | \$ 3,028.00            | ✓       |
| 2                           | REAR DOOR OUTER SEAL - RH <i>new</i>          | 1   | \$ 151.00              | ✓       |
| 3                           | REAR DOOR CATCH <i>?</i>                      | 1   | \$ 134.00              | ?       |
| 4                           | REAR DOOR COVER - RH <i>new</i>               | 1   | \$ 368.00              | ✓       |
| 5                           | FRONT DOOR - RH <i>Dented</i>                 | 1   | \$ 3,028.00            | ✓       |
| 6                           | FRONT DOOR OUTER SEAL - RH <i>new</i>         | 1   | \$ 185.00              | ✓       |
| 7                           | FRONT DOOR CATCH <i>?</i>                     | 1   | \$ 134.00              | ?       |
| 8                           | FRONT DOOR COVER - RH <i>new</i>              | 1   | \$ 390.00              | ✓       |
| 9                           | REAR BUMPER GUIDE SECTION - RH <i>Not new</i> | 1   | \$ 71.00               | x       |
| 10                          | REAR WHEEL COVER - LH / RH <i>new</i>         | 2   | \$ 1,132.00            | ✓       |
| 11                          | REAR WHEEL HOUSING LINER <i>new</i>           | 1   | \$ 262.00              | x       |
| 12                          | REAR BUMPER INSERT <i>new</i>                 | 1   | \$ 107.00              | x       |
| 13                          | SUNDRIES <i>?</i>                             |     | \$ 400.00              | ?       |
| <b>TOTAL SPARE PARTS</b>    |                                               | :   | <b>\$ 9,390.00</b>     |         |
| <b>TOTAL LABOUR CHARGES</b> |                                               | :   | <b>\$ 10,352.00</b>    |         |
| <b>GRAND TOTAL</b>          |                                               | :   | <b>\$ 19,742.00</b>    |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian King*  
SURVEYED DATE : *10/08/22*  
AUTHORISED DATE :  
EXCESS COST :  
LIABILITY :  
REMARKS : *Not Authorised, 06 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT