

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 11 Aug 2022)**Parts:** 143 HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHA8850K/11/08/2022 13:53**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	20.00	0.00	Ry *1,052.20 FL
2	1		*FRONT BUMPER BRACKET LH	20.00	0.00	? *24.60 FL
3	1		*FRONT FENDER LH	20.00	0.00	At *663.00 FL
4	1		*FRONT DOOR PANEL	20.00	0.00	*2,707.70 FL
5	1		*FRONT DOOR PANEL LH	20.00	0.00	Ry *2,707.70 FL
6	1		*FRONT LH ROCKER PANEL	20.00	0.00	Rx *732.80 FL
7	1		*FRONT LH WHEEL COVER	20.00	0.00	any *217.20 FL
8	1		*FRONT DOOR COMFORT STICKER	0	0.00	me *75.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$) **8,180.20**- List Item Discount on L Items (\$\$) **1,621.04**Total Parts (\$\$) **6,559.16**

ComfortDelGro Engineering Pte Ltd/SHA8850K/11/08/2022 13:53. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	525 700.00
2	SPRAY PAINTING	New	750 900.00
3	TRANSFER DOOR PART TO NEW DOOR	New	X 90.00
4	CHECK WIRING & LIGHTING	New	X 60.00
Gross Labour Cost (S\$)			1,750.00

ComfortDelGro Engineering Pte Ltd/SHA8850K/11/08/2022 13:53. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tan/Ch 9749 5749
WP 11/8/22 @ 4pm
1/3 Resurvey after repair
Tan/Ch 11/8/22
2-3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:


eam: ARC Repair TP(CFS0)1 JOB CARD Sales Order: 4524946 JC NO: 805526201

CUSTOMER CITYCAB PTE LTD R/MS 7010070 CUSTOMER NO. 383 SIN MING DRIVE ADDRESS Singapore SINGAPORE 575717 L. (R) 65551188 (O) (P) SCOUT CARD NO.	REGN NO: SHA8850K	MILEAGE
	MAKE: HYUNDAI	FUEL E.....1/2.....F
	MODEL I-40	DATE/TIME IN 11.08.2022 10:30
	YR OF MANU. 29.09.2016	TARGET DATE
	CHASSIS CODE RMHLB41UMGU093845	COMPLETION DATE/TIME:

ccident Date: 10.08.2022
ATURE: ACCIDENT REPAIR (AR)

JOB DESCRIPTION

/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR CUSTOMER'S SIGNATURE

nowledgement Slip

Exit Pass

3:
O.:
le No.: SHA8850K CHIANG

Vehicle No.: SHA8850K

3 of Service Advisor Signature/Date Name of Service Advisor Date

returned to Service Reception upon collection To be kept by Security Guard