2/13/23, 4:54 PM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIS22007640/UPA3Q2

**Date:** 13/02/2023

**REFERENCE** 

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No: SP0001024186

Claimant Vehicle GBK8888X Insured Vehicle No: YM8914X

No: GDN0000A Insured vehicle No: YIVI0914A

Date of Loss: 06/08/2022 Nature of Claim: TP Claim No: 202222006048

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: GBK8888X

Make & Model: NISSAN NV350, 2.5 5MT 5DR EURO V (A) Engine No: YD25361111A

Reg. Date: 23/07/2015 (Man. Year: 2014) Chassis No: JN1MC2E26Z0003973

Colour: Grey Odometer: 152415 km

Engine Capacity: 2488 cc
Market Value/New Car

Market Value/New Car
Price:
N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15
Front Left Side: Michelin 8 mm Rear Left Side: Michelin 8 mm
Front Right Side: Michelin 8 mm Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,156.10	1,385.86	2,770.24	66.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,870.00	1,120.00	750.00	40.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,026.10	2,505.86	3,520.24	58.42
Approved Total (Overridden) (S\$)		2,000.00		
(S\$)	6,026.10	2,000.00	4,026.10	66.81
+ GST 7.00/7.00% (S\$)	421.83	140.00	281.83	66.81
Nett Amount (S\$)	6,447.93	2,140.00	4,307.93	66.81
+ Loss of Use (3.0 x	S\$80.00/day) (S\$)	240.00		
+ Doc	c/Search Fee (S\$)	2.00		
	Nett Liability (S\$)	2,382.00		
Global Sur	m Settlement (S\$)	2,380.00		

**INSPECTION** 

Date of Assignment: 11/08/2022

Fastech Auto Pte Ltd (HQ)

Date Inspected: 15/08/2022 Inspected At: 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay

Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

2/13/23, 4:54 PM Adjuster Report

### **REPAIR DETAILS**

Reference

Part Source: (Last Synchronised: 13 Feb 2023)

Parts: N/A NISSAN NV350 2.5 5MT 5DR EURO V (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBK8888X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILLAMP O/S	Broken	389.10 F	*224.80 FL
2	1		*REAR BUMPER	Deformed	931.00 F	*720.60 FL
3	1		*REAR FENDER O/S	Repair	2,201.00 F	*- FL
4	1		*SET REAR BUMPER CLIPS	Necessary	35.00 FS	*35.00 FS
5	1		*REAR FENDER CORPORATE STICKER O/S	Necessary	600.00 FS	*500.00 FS
F=Fra	ınchise	part. S=SpcN	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	4,156.10	1,480.40
			- List Item Discount on L Item	s 0.00/10.00% (S\$)	0.00	94.54
				Total Parts (S\$)	4,156.10	1,385.86
			Report was unsubmitted during this	print-out.		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labe	our Items			
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REFIX REAR REVERSE SENSOR	New	80.00	50.00
3	TO SPRAY RUST PROOFING	New	40.00	0.00
4	TO RESET & REPROGRAMME SYSTEM	New	100.00	0.00
5	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	800.00	550.00
6	TO PUTTY & SPRAY PAINTING	New	800.00	500.00
		Gross Labour Cost (S\$)	1,870.00	1,120.00
	Report was unsubm	itted during this print-out.		

< END OF ESTIMATES >