

LKK acilia

Not Authorized
her

15/8/22

2/5 \$2000
3 days.

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No : 200006262D

VEHICLE No: GBK 8888X

NETT ITEM

1PC	TAILLAMP O/S	224.80	520	\$389.10	✓
1PC	REAR BUMPER	720.60	2e	\$931.00	✓
1PC	REAR FENDER O/S		2	\$2,201.00	X
				\$3,521.10	

10%

S.NETT

1SET	REAR BUMPER CLIPS	Mer	\$35.00	✓
	REAR FENDER 'CORPORATE' STICKER O/S	Mer	\$600.00	500

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REFIX REAR REVERSE SENSOR	\$80.00	50
TO SPRAY RUST PROOFING	\$40.00	X
TO RESET & REPROGRAMME SYSTEM	\$100.00	X
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$800.00	550
TO PUTTY & SPRAY PAINTING	\$800.00	500
TOTAL	\$6,026.10	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

p-945-4
102
850.80
535
1120
2505.80
202
2004.