

Date: 11/08/2022

Vehicle No: SMY3718H

Model: TOYOTA SIENTA HYBRID 1.5G

Chassis: NHP1707180504

Reg.Year: 2019

Third Party Insurer: CHINA TAIPING

Third Party Veh No: SMS4153L

Date of Accident: 11/08/2022

Estimator: KIT

Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		By \$1,131.00
2	REAR TAILGATE WINDSCREEN MOULDING	1		na \$110.00
3	REAR TAILGATE WIPER ARM	1		na \$104.00
4	REAR TAILGATE WIPER MOTOR	1		\$773.00
5	REAR TAILGATE "LOGO" EMBLEM	1		na \$80.00
6	REAR TAILGATE "HYBRID" EMBLEM	1		na \$80.00
7	REAR TAILGATE LAMP LH	1		\$359.00
8	REAR TAILGATE LAMP RH	1		\$359.00
9	REAR TAILGATE OUTER GARNISH	1		na \$288.00
10	REAR TAILGATE MECHANISM LOCK	1		na \$410.00
11	REAR TAILGATE INNER HANDLE COVER	1		\$68.00
12	REAR TAILGATE INNER TRIM BOARD	1		\$155.00
13	REAR TAILGATE WEATHERSTRIPE	1		\$145.00
14	REAR TAIL LAMP LH	1		na \$435.00
15	REAR TAIL LAMP RH	1		na \$435.00
16	REAR BUMPER	1		By \$418.00
17	REAR BUMPER SIDE RETAINER LH	1		na \$70.00
18	REAR BUMPER SIDE RETAINER RH	1		na \$70.00
19	REAR BUMPER OUTER GARNISH	1		By \$190.00
20	REAR BUMPER SIDE GARNISH LH	1		na \$129.00
21	REAR BUMPER SIDE GARNISH RH	1		na \$129.00
22	REAR BUMPER REFLECTOR LH	1		na \$60.00
23	REAR BUMPER REFLECTOR RH	1		na \$60.00
24	REAR BUMPER ANTENNA SENSOR	1		\$92.00
25	REAR END PANEL	1		\$433.00
26	REAR END PANEL TOP GARNISH	1		\$148.00
27	REAR END PANEL LOCK STRIKER	1		na \$35.00
28	REAR FLOOR PANEL	1		\$704.00
29	REAR FLOOR PANEL TOOLBOX TRAY	1		\$447.00
30	REAR FLOOR PANEL TOP CARD BOARD	1		\$280.00
31	REAR FENDER INNER TRIM BOARD LH	1		\$627.00
32	REAR FENDER INNER TRIM BOARD RH	1		\$627.00
SUB TOTAL				\$9,451.00
LESS 25%				-\$2,362.75
PARTS TOTAL				\$7,088.25

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 11/08/2022
Vehicle No: SMY3718H
Model: TOYOTA SIENTA HYBRID 1.5G
Chassis: NHP1707180504
Reg.Year: 2019

Third Party Insurer: CHINA TAIPING
Third Party Veh No: SMS4153L
Date of Accident: 11/08/2022
Estimator: KIT
Surveyor:

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE WINDSCREEN SEALANT	1		<i>na</i> \$80.00
2	REAR TAILGATE INNER TRIM BOARD CLIPS	1		<i>na</i> \$40.00
3	REAR NUMBER PLATE WITH HOLDER	1		<i>na</i> \$50.00
4	REAR BUMPER CLIPS	1		<i>na</i> \$50.00
5	REAR BUMPER REVERSE SENSOR	1		\$300.00
6	REAR END PANEL JOINT SEALANT	1		\$80.00
7	REAR END PANEL TOP GARNISH CLIPS	1		<i>na</i> \$30.00
8	REAR FENDER INNER TRIM BOARD CLIPS LH	1		\$50.00
9	REAR FENDER INNER TRIM BOARD CLIPS RH	1		\$50.00
			S/N TOTAL	\$730.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST ACCIDENT AREAS. \$1,200.00 *7*

LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT ACCIDENT AREAS. \$1,000.00 *600*

LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS. \$120.00 *✓*

LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS. \$120.00 *60*

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR. \$100.00 *50*

TO TUFF KOTE & UNDERSEAL MATERIALS. \$150.00 *80*

TO DIAGNOSIS FAULT CODE & RESET MEMORY. \$120.00 *7*

TO CHECK WIRING & ELECTRICAL DIAGNOSTIC \$80.00 *20*

LABOUR TOTAL \$2,890.00

KIT TOTAL \$10,708.25

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

