33. SC. B13. 4 CM 10-C	2007645 (Rvy3 609m
<u>AS</u>	SIGNMENT
oni = Date:	Veh No: CBU 23884 Yr Regn: 2017 Jun
sin z≥ki Cost:	Type: M.Car / M.Cycle / Bus / Aar / Lorry / Taxi / Prime Mover /
TH WS/TP RES/OD RES/EVA/INV/MV	Truck/Trailer or
In-Sect Vehicle No: GBG 2758	Make: PEUGEN PARNOLLZ IN AT C.C 1560
Washiop m/s THINK ONE	Colour WHITE A/C: Insured/Std/NI/NA
LO JLN LAM HUMT #02-32	Sp.Reading 197135 T/Radio: Insured / Std / NI / NA
sured SMP	Eng/No:
olicy N.	C/Na: VF 37 FBHYN43884344
airnes lb.	Gen. Cond: Good /Fait / Poor / Burnt
um lasred: Excess:	Steering: Voorder / Jammed / Leaked / Burnt or
(Client Record)	Brake: Anorder / Jammed / Leaked / Burnt or
Aake of Veh:	Modi : NII/ I S/Rim: I STD A/Rim or
	Tyre Size: F: 185 boky
(PolicyCondition)	I USTOCKS
RemarkThe veh had commenced its N/S O/S	BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/
repair at the time of inspection.	TOYOTYOKO or RADIAL
Sail or Narket Value: 29 K	Front Rear
DAC Acident Rport: Consistent? : Yes or No	ORal Draw
GIA / PR Seen: Consistent?: Yes or No	1/Rei
Est Repirs: days Res.: Yes or No	D.O.A. 28 107 12 D.O.I. 12/08/22
Lerm Surm: % 3 Val.: Yes or No	Survey held at THINKONE
	Des. of Damages : Frt. / Rear / G/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS Vehicle: IN / OL	
Date: Person Contacted:	The U/S / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
REPAR LIMIT-21K	
0	
ale/Time, Fie Pass to?	
	Days Of Repair:
: Final Report	Resurvey No. of Trip: Survey Fee:
	Transportation:
Add Fe	
	Interview (\$) Photos
Report Format :	: Tech. Invs (\$) Others

Singapore 720002

ESTIMATED

GDG.	2358	U PEUGEOT	DATE	08.08	.2022
No		DESCRIPTION			10UNT S\$
	1	FRONT BONNET			2,127.00
1	-	RADIATOR GRILLE TOP PANEL			1,073.00
2	1	RADIATOR GRILLE TO TARLE /			1,125.00
3	1	PADIATOR TOP CRILLE (LOCO)			298.00
4	1	RADIATOR TOP GRILLE (LOGO) X RADIATOR SUPPORT PANEL X			1,655.00
5	1	EDONT DUMPED BEDIEODCEMENT			1,120.00
6	1	FRONT BUMPER REINFORCEMENT / FRONT BUMPER & /			1,813.00
7 8	1	FRONT BUMPER FOG LAMP COVER 19-14	299.00		598.00
9	2 1	FRONT BUMPER LOWER GRILLE COM/	200.00		917.00
10	2	FRONT BUMPER LOWER GRILLE MOULDING R+L	285.00		570.00
11		FRONT BUMPER SIDE RETAINER LH	330.00		660.00
12	2	FRONT HEADLAMP PANEL RH			255.00
13	1	FRONT FENDER RH 64/			920.00
	1	FRONT FENDER COVER RH			98.00
14 15	1	FRONT FENDER SIGNAL LAMP RHM14			89.00
	1	FRONT FENDER UNDER LINER LH			285.00
16	1	FRONT FENDER INNER PANEL LH			955.00
17	1	WIPER WASHER TANK C/W MOTOR Je			952.00
18	1	WASHER TANK C/W MOTOR /~			45.00
19	1	POWER STEERING PUMP X			2,500.00
20	1	FRT SHOCK ABSORBER LH			850.00
21 22	1	WHEEL RIM FERRI AND REL	320.00		640.00
22	1	WHEEL KIN	020.00	\$	19,965.00
	- N	LESS 1	0%	\$	1,996.50
	- 1	LEGS	.070	\$	17,968.50
No	Qty			Al	MOUNT S\$
No 1	Qty 1	FRONT HEADLAMP RH Cm		Al	2,250.00
1 2		FRONT HEADLAMP RH Crow FRONT NUMBER PLATE W/CASE		Al	2,250.00 40.00
1	1	FRONT HEADLAMP RH Cm	210.00		2,250.00 40.00 420.00
1 2	1	FRONT HEADLAMP RH Crow FRONT NUMBER PLATE W/CASE	210.00	Al	2,250.00 40.00
1 2	1	FRONT HEADLAMP RH CM FRONT NUMBER PLATE W/CASE X TYRE 185/60/15 X LABOUR & MISCELLANEOUS:		\$	2,250.00 40.00 420.00 2,710.00
1 2 3	1	FRONT HEADLAMP RH Crown FRONT NUMBER PLATE W/CASE TYRE 185/60/15 CLABOUR & MISCELLANEOUS: To remove damaged body parts with all necessary components/attach-		\$	2,250.00 40.00 420.00 2,710.00
1 2 3	1	FRONT HEADLAMP RH CM FRONT NUMBER PLATE W/CASE X TYRE 185/60/15 X LABOUR & MISCELLANEOUS:		\$	2,250.00 40.00 420.00 2,710.00
1 2 3	1	FRONT HEADLAMP RH Crown FRONT NUMBER PLATE W/CASE X TYRE 185/60/15 X LABOUR & MISCELLANEOUS: To remove damaged body parts with all necessary components/attachments apply hot-works where necessary repair, reshape body dented		\$	2,250.00 40.00 420.00 2,710.00
1 2 3	1	FRONT HEADLAMP RH Crown FRONT NUMBER PLATE W/CASE TYRE 185/60/15 CLABOUR & MISCELLANEOUS: To remove damaged body parts with all necessary components/attachments apply hot-works where necessary repair, reshape body dented panels in accordance with factory specifications replace new parts refine the parts of the components of the compo		\$	2,250.00 40.00 420.00 2,710.00
1 2 3 No	1	FRONT NUMBER PLATE W/CASE TYRE 185/60/15 LABOUR & MISCELLANEOUS: To remove damaged body parts with all necessary components/attachments apply hot-works where necessary repair,reshape body dented panels in accordance with factory specifications replace new parts refi and align into position refit all necessary components/attachments		\$	2,250.00 40.00 420.00 2,710.00 MOUNT S\$ 1,600.00
1 2 3	1	FRONT NUMBER PLATE W/CASE TYRE 185/60/15 LABOUR & MISCELLANEOUS: To remove damaged body parts with all necessary components/attachments apply hot-works where necessary repair,reshape body dented panels in accordance with factory specifications replace new parts refi and align into position refit all necessary components/attachments To spray paint replaced/repaired body parts inclusive of preparatory		\$	2,250.00 40.00 420.00 2,710.00 MOUNT S\$ 1,600.00
1 2 3 No 1	1	FRONT NUMBER PLATE W/CASE TYRE 185/60/15 LABOUR & MISCELLANEOUS: To remove damaged body parts with all necessary components/attachments apply hot-works where necessary repair,reshape body dented panels in accordance with factory specifications replace new parts refi and align into position refit all necessary components/attachments To spray paint replaced/repaired body parts inclusive of preparatory works and painting materials	t	\$	2,250.00 40.00 420.00 2,710.00 MOUNT S\$ 1,600.00
1 2 3 No	1	FRONT NUMBER PLATE W/CASE TYRE 185/60/15 LABOUR & MISCELLANEOUS: To remove damaged body parts with all necessary components/attachments apply hot-works where necessary repair,reshape body dented panels in accordance with factory specifications replace new parts refi and align into position refit all necessary components/attachments To spray paint replaced/repaired body parts inclusive of preparatory works and painting materials To remove,refix- rediator,air con condenser with all necessary components	t	\$	2,250.00 40.00 420.00 2,710.00 MOUNT S\$ 1,600.00
1 2 3 No 1	1	FRONT NUMBER PLATE W/CASE TYRE 185/60/15 LABOUR & MISCELLANEOUS: To remove damaged body parts with all necessary components/attachments apply hot-works where necessary repair,reshape body dented panels in accordance with factory specifications replace new parts refi and align into position refit all necessary components/attachments To spray paint replaced/repaired body parts inclusive of preparatory works and painting materials	t	\$	2,250.00 40.00 420.00 2,710.00 MOUNT S\$ 1,600.00
1 2 3 No 1	1	FRONT NUMBER PLATE W/CASE TYRE 185/60/15 LABOUR & MISCELLANEOUS: To remove damaged body parts with all necessary components/attachments apply hot-works where necessary repair,reshape body dented panels in accordance with factory specifications replace new parts refi and align into position refit all necessary components/attachments To spray paint replaced/repaired body parts inclusive of preparatory works and painting materials To remove,refix- rediator,air con condenser with all necessary components to faciliate repair work	t nents/	\$	2,250.00 40.00 420.00 2,710.00 MOUNT S\$ 1,600.00
1 2 3 No 1	1	FRONT NUMBER PLATE W/CASE TYRE 185/60/15 LABOUR & MISCELLANEOUS: To remove damaged body parts with all necessary components/attachments apply hot-works where necessary repair,reshape body dented panels in accordance with factory specifications replace new parts refi and align into position refit all necessary components/attachments To spray paint replaced/repaired body parts inclusive of preparatory works and painting materials To remove,refix- rediator,air con condenser with all necessary components to faciliate repair work To conduct headlamp alignment	t nents/	\$	2,250.00 40.00 420.00 2,710.00

	\$ 3,350.00
Ü	\$ 17,968.50

\$60 go.00

LIST PARTS	\$ 17,968.50
SN PARTS	\$ 2,710.00
LABOUR	\$ 3,350.00
E E E	\$ 24,028.50

LKK Auto Consultants hence notify the Repairer of the following:

. To resurvey before/after spray painting

- . To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rame Hp 9001 0068 7 days 12/08/22 @1530
Rosey after reprise
Regard algorit
copy ST0Y22880002-03 / THINK ONE AUTOCARE PTE LTD ENTRY DATE & TIME: 08/08/2022 13:28 (SGT) SUBMITTED BY: Ng Shee Pan VERSION: 4 (08/08/2022 14:40 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Please report <u>correctly</u> the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 08/08/2022 13:28 (SGT) Reported by Date of Accident 28/07/2022 18:40 (SGT) Exact Location of Accident Bukit Batok West Ave. 8, Singapore Additional Location Information **BUKIT BATOK WEST AVENUE 8** Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Peugeot

Vehicle Registration Number GBG2358U

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner THINK ONE LEASING PTE LTD Company Reg No 2XXXXX609M Email Address raj@tol.com.sg Mobile Phone No (Phone) +65-96788288 Alternative Phone No

VEHICLE PARTICULARS

Manufacturer

Model Partner Variant VAN Exact purpose for which vehicle was being used at time of accident **Employment** Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party Vehicle Category Commercial vehicle Transmission Manual 1600

INSURANCE COMPANY

Name of Insurance Company Tokio Marine Insurance Singapore Ltd Policy Number / Cover Note Number 20-ML000183-R00

DRIVER

Name of Driver SARASVATHY NRIC No SXXXX080C Date Of Birth 24/11/1982 Occupation Outdoor

Date Of Driving Pass 13/06/2022 **Driving experience** 1 MONTH Gender Female Mobile Number (Phone) +65-97330854 Alt. Phone Number Email Address raj@tol.com.sg Address APT BLK 339 BUKIT BATOK STREET 34 Address complement #04-294 Postcode management and a second 850339 Is the driver the policyholder? No If No, Relationship of the Driver with the Insured Hirer Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Collision - Major/Minor Rd Type of Accident Weather Conditions Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was anybody injured in the Accident? Yes Was any injured conveyed to hospital by ambulance? No Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) 1 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement DETAILS OF POLICE ACTION Was the accident reported to the police? Police Station Name Hong Kah North Neighbourhood Police Post Police Station Phone No (Phone) +65-18005679999 Alt. Police Station Phone No (Fax) +65-65652508 Police Station Address Blk 370 Bukit Batok Street 31 #01-201 Singapore 650370 Was notice of intended Prosecution given? If yes, against whom? CIRCUMSTANCES OF ACCIDENT PLEASE REFER TO ATTACHMENT ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No **DETAILS OF OTHER VEHICLE PROPERTY 1** Vehicle Registration Number SG5960J Vehicle Manufacturer Man Vehicle Model BUS

Vehicle Variant

Vehicle Colour	Green
Vehicle Category	Bus
Name of Driver	CHONG KIM KON
Contact Number	-
Address	
Address complement	_
Postcode	
Insurance Company Name	-
Nature Of Damage	
Details of property damaged in accident	NOT SURE
No. Of Passenger (Including Driver)	NOT SURE

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	SARASVATHY
Gender	Female
Phone No	(Phone) +65-97330854
Address	APT BLK 339 BUKIT BATOK STREET 34
Address Complement	#04-294
Post Code	650339
Approximate Age Years Old	· · · · · · · · · · · · · · · · · · ·
Injuries Sustained	BODY
Injured person in which vehicle?	GBG2358U
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

mong but from alter lane from buril batok road ((1BG 2308U)
the juniture when I was filtering out	
here was no vehicle coming towards the or seen anywher	e nearby
2 this was at the time (margint) I was filtering out	
Howe no idea where the smitt but safated came from	or (service he gas)
I was to take lost and transmansed when this happene	I and women's late
& was I size to reput	
as tages i entro by types	
	DO+15 8/8/22
	Time 12:12 hrs
	Christian
	C62320807
	ALLARA
	- HUNNY
	4-4-
	li li
	P


Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Data & Timo

Witnessed by Reporting Centre Personnel



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company	Ì
Owner ID:	60994	
		į
Vehicle No.:	GBG2358U	
Vehicle to be Exported:	No.	
Intended Deregistration Date:	15 Aug 2022	
Vehicle Make:	PEUGEOT	
Vehicle Model:	PARTNER L2 1.6 AT	
Primary Colour:	White	
Manufacturing Year:	2016	
Engine No.:	10JBHW3008903	
Chassis No.:	VF37FBHYMGJ884344	
Maximum Power Output:		
Open Market Value:	\$19,245.00	
Original Registration Date:	30 Jun 2017	
First Registration Date:	30 Jun 2017	
Transfer Count: -	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
Actual ARF Paid:	ı \$963.00 .	
PARF Eligibility:	No TERRITOR AND RESIDENCE OF THE PROPERTY OF T	
PARF Eligibility Expiry Date:		
PARF Rebate Amount:	SO.CO TO THE RESERVE BY THE PROPERTY OF THE PR	
COE Expiry Date:	29 Jun 2027	
COE Category:	C - Goods Vehicle & Bus	į
COE Period(Years):	10	ĺ
QP Paid:	\$36,879.00	
OE Rebate Amount:	\$17.978.00	
otal Rebate Amount:	\$17,978.00	

The information contained herein is correct as at 15 Aug 2022

OK

Peugeot Partner 1.6A HDi

Overview

Financial-

Accessories

Similar

Research

Photos

Map







Price

\$42,800

Lifespan 🙄

28-Nov-2037

Depreciation (1)

\$8,090 /yr View models with similar depre

Reg Date

29-Nov-2017

(5yrs 3mths 13days COE left)

Mileage

145,000 km (30.8k /yr)

Manufactured •

2017

Auto

Road Tax

N.A.

Transmission

Dereg Value

\$18,827 as of today (change)

Fuel Type

Diesel

COE

\$35,587

OMV |

\$20,654

Engine Cap

1,560 cc

ARF

\$1,033

Curb Weight 1,460 kg

No. of Owners