

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No: 53231488C GST Reg No : 53231488C

Blk 1 Kaki Bukit Ave 6

11/8/2022

01-43

Singapore 417883

Accident date: 11/08/2022

Estimated repair cost for vehicle no: SDX3236T HYUNDAI CN7 AVANTE 1.6 DOHC

CHASSIS: KMHLN41ETNU192526 (2021)

S/n	Qty	Items	U/price	Amount
1	1	REAR BOOTLID TOP GARNISH <i>cut</i>	\$397.10	\$ 397.10 ✓
2	1	REAR BOOTLID LOWER GARNISH <i>new</i>	\$358.80	\$358.80 ✓

TOTAL :	\$516.60
LESS 20 %	\$103.32
SUB-TOTAL :	\$413.28

397.10

Supplementary: 317.68