



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
CYCLE & CARRIAGE LEASING PTE LTD	Cust No/Name KC000162/ CYCLE & CARRIAGE LEASING PTE L
239 ALEXANDRA ROAD	Reg No/Reg Date SMU4161C / 13/08/202
SINGAPORE 159930	Date In/Mileage / 0
Contact No Mobile: 91185739	Chassis No MMBXTA03AMH000287
	Engine No 3A92UJX0477
	Make/Model MIT/21MY SPACE STAR 1.2 CVT (E12)
	Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	30/07/2022/ 09:48	TLK	282 / Kevin Leong	25732			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								640 / 1920.00
REPLACE REAR BUMPER PANEL & AFFECTED AREA								
REPAIR ON REAR LH FENDER								550 / 1650.00
E PNT98000								80 / 150.00
PAINT WORK ON REAR BUMPER & REAR LH FENDER								
E PNT88000								X 100.00
REMOVE & INSTALL REAR PARKING ASSIST FOR FACILITATE REPAIR								X 100.00
M SUNDRY								
PERFORM RUST PREVENTION								
M SUNDRY								120 / 150.00
TO APPLY SEALANT ON AFFECTED AREA								
A 54900099								280.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								
A 10028901								70 / 50.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
M SUNDRY								
SUNDRIES								
M FACE,RR BUMPER					1.00	598.00	00.00	598.00
M BRACKET,RR BUMPER SIDE,LH					1.00	10.00	00.00	10.00
M BRACKET,RR BUMPER					1.00	69.00	00.00	69.00
M REFLECTOR,LH					1.00	48.00	00.00	48.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudices" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Star (LKK)
5/8/22, 9.30am

P/P
4 BL 7
3 45

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirm & accepted by

Acknowledged by Repairer

Signature:

Date:

7% GST on 5125.00 358.75

Nett 5,125.00

Total Payable 5,483.75

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.