

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
CYCLE & CARRIAGE LEASING PTE LTD	Cust No/Name KC000162/ CYCLE & CARRIAGE LEASING PTE L
239 ALEXANDRA ROAD	Reg No/Reg Date SMU4161C / 13/08/202
SINGAPORE 159930	Date In/Mileage / 0
Contact No Mobile: 91185739	Chassis No MMBXTA03AMH000287
	Engine No 3A92UJX0477
	Make/Model MIT/21MY SPACE STAR 1.2 CVT (E12)
	Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00041	Cash	30/07/2022/ 09:48	TLK	282 / Kevin Leong	25732		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							1920.00
REPLACE REAR BUMPER PANEL & AFFECTED AREA							
REPAIR ON REAR LH FENDER							
E PNT98000							1650.00
PAINT WORK ON REAR BUMPER & REAR LH FENDER							
E PNT88000							150.00
REMOVE & INSTALL REAR PARKING ASSIST FOR FACILITATE REPAIR							
M SUNDRY							100.00
PERFORM RUST PREVENTION							
M SUNDRY							100.00
TO APPLY SEALANT ON AFFECTED AREA							
A 54900099							150.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							
A 10028901							280.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							
M SUNDRY							50.00
SUNDRIES							
M FACE,RR BUMPER				1.00	598.00	00.00	598.00
M BRACKET,RR BUMPER SIDE,LH				1.00	10.00	00.00	10.00
M BRACKET,RR BUMPER				1.00	69.00	00.00	69.00
M REFLECTOR,LH				1.00	48.00	00.00	48.00

Confirm & accepted by

	Nett	5,125.00
7% GST on	5125.00	358.75
Total Payable		5,483.75

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.