



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:VALE OH		Ref: CC4/ASM22007670/Upa3q2 Date: 07/02/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 7019B	Veh. Inspected	FBQ 9256G
Policy No.	P2465679	Coverage (\$)	0.00
Claim No.	S2M0489D	Excess (\$)	0.00
Assign From		Assign Date	12/08/2022
2. Vehicle Particulars & Condition			
Make & Model	HONDA CB190SS	c.c	184
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	LWBPCL300K1005219	Colour	BLACK
Odometer	347456 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	100-80-17	MICHELIN	8 mm
L/H Front Tyre			mm
R/H Rear Tyre	130-70-17	MICHELIN	8 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	04/08/2022	Inspection Date	12/08/2022
Survey held at	EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	